SURVEY & REMONUMENTATION

APR 2 4 1995

expressed below:

on this certificate.

LAND CORNER RECORDATION CERTIFICATE

	COVINED	VECO	NUALIO	IN CEL	, i ili	CAIL
Zilina	Requirem	ant of	Act 74	Mich	DΑ	1070

PA Of 1990 Co.	i 4
MEL AMIS	RIS

LENCA LAND SURVEYOR

ERED LAHO

REVISEO JAN., 1983

Eor	corners in COMM	ISSIO	V Filing Requir	rement of Act 74, Mich.	P.A. 1970) 1/9	167.	7NG	Cha	irmen					
101	MENOMINEE		Located In:	Corner Code ##				E Z) } }	္	20) 1		
	(County)			0001 0000 -7-7				57	2(ii) >>	. ;	3	KEUEIYEB	1		
1.	Public Land Survey		T_37N_R _25W	M-2						<u>, , , , , , , , , , , , , , , , , , , </u>	ý				
									<u> </u>	'	7	<u> </u>) }		
			T R		ļ				<u> </u>	۾ ڇ	===				
9	Property Controlling	S	T R					30.00 30.00 30.00	i二 3 (の)	₹ ?	5	KECORO			
۷.	in Section							3	' <u>S</u> ~	۲ م	-	63	•		
3.	Miscellaneous				Re	gister	of [Deeds	s Sta	-	ፓን ጼፑ	ile N	lum	ber	
	Property in Sec.	s	T R	·					·		,				_
4	Lot No	Recorded	Plat							: *		· .			
							В	C () E	F	G I	HI	J	<u>к</u>	뉴
•						2	- 6-	┼- ∮	+	- 4	-	} 	½	-	-{-
						3	+	+	+	+	├	\vdash	-		+
						4	- {-	╁	+		1	┝┤	11	-	-12-
				Oct 12 , 19 , 19 , 19		5_	+	++		+-	 		+	\dashv	十
	-	•	• •	nd rules therefore as required		6 -	-18- 	1-17	/	-1'6 	-1	5	14	_	-13-
				rtment of the Interior, Bureau o er points mentioned in lines 3,		7	+	11	1	 	_		22	\top	+

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

1847: Original Survey (Township Lines) by Henry Floyd - B.T.'s - Cedar, 06"- N54°W, 13 lks; Spruce, 5" - S43°E - 16 lks. All original evidence for this corner has been destroyed by logging activities.

1968: L.C.R.C. No. 676-Vol 3 by Frank J. Bray, DNR Surveyor, states that a 1" dia. Iron Pipe/4" dia. Alum. cap was replaced from a scribed wood post set by M. McNabb in 1918 from original B.T. This B.T. has been chopped out and is down. Point of older wood post was found alongside scribed post. Blazed and squared trees near. - New B.T.'s - 6" Cedar - N37°E - 09.5 lks; 8" Cedar - S30°W, 07 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a 1" dia. Iron Pipe/4" dia. Alum. cap and 2 Bearing Trees as described in part "A". Both DNR B.T.'s were found in good condition. We placed a nail in the sides of the existing B.T.'s and re-used them. Since the DNR distances were to the face of the trees, our distances are slightly longer. Since Marcus McNabb set his post from an original B.T. and the DNR Monument was placed in the location of the McNabb Post, we accepted the DNR Monument as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner of Miles Accepted existing 1"dia. Iron Pipe/3-1/4" dia. Alum. cap stamped for corner location:

9" dia. Cedar - (Ex. B.T.)	N45 ⁰ E	6.63 feet	Scr. NBT
8" dia. Cedar	S410E	22.20 feet	Scr. NBT
12" dia. Cedar - (Ex. B.T.)	S40°W	5.20 feet	Scr. NBT
12" dia. Spruce	N510W	15.71 feet	Scr. NBT
Survey Sign Post	N90°E	1.5 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Jane	Nov. 15, 1994
Surveyor's Michigan License No	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 1975