CONS. 4047

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 37 NR 27 W

				-			Menomir		C	OUNTY
DESCRIPTION	O	CORNER	1/4 corne	r bet	ween S	<u>}ectio</u> r	ng 20 ar	nd 29.		
DESCRIPTION	OF	CORNER	MONUMENT	L_j	Pipe w	vith 4	Brass	Çap.		
WITNESSES	ŢΟ	CORNER .	7" Cedar_	<u>s</u>	37 A T	73.	Links,	narked	1/4 9	NOT_
			_ 7"_ Cedar							
				- -			- -			. -
					-	<u></u> -		- -		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Tamarack B.T. bearing S 59 W, 25 Links; stump badly splintered. Found overgrowth of face and notch. Also found Tamarack stump bottom bearing N 52 E, 9 Links.

Corner found by Forestry Division Survey Crew.

Corner lies 23 Links, north of Power Line and 60 links south of approximate center line of County Road.

Corner was placed and witnessed on 27 June 1958 with C. Limpert, District Forester.

SURVEYORS SEAL

Billy D. Buchles

Billy D. Buchler DATE 4-03-59