APR 0 6 1999

ية الأسلام المستهدر والمن المستهدد المناس	•					Z BAUK	KLS	
SECTION	LAI	ND CORNER	RECORDATION	CERTIFICA	ATE	Chairman		
For corners in	Fi	lling Requirer	nent of Act 74, Mi	UII. P.A. 19		3 0		
		_	~ 1 #		in the second se	99.	Ž.	
MENOMINEE	Located in:	Corner	r Code #		300 300	S N	RECEIVED FOR	
(County)	374				活点の	2	8	
1. Public Land Survey		R <u>27W</u>	B-13		193	(3 o	2	
•		R			÷ j	is a		
		R <u>27 </u>	8-1			\sim $\tilde{\mathcal{H}}$		
2. Property Controlling	s t	R -			<u> </u>	િં	20 1000 20 1000 20 1000	
in Section	S T	R			AS.	. വ		
3. Miscellaneous	S T	R						
Property in Sec.	S T	R			Register of De	eds Stam	& File N	umber
					•			
4. Lot No, Record	ed Plat			_	a o c n i		т ј	K I.
5. Private Claims					1 7 7 7			ŤĪ
	a.				2 - 6 - 5 -		32-	
•					3			+
I, William Lenca	in a field survey of	on _Dec. 17	, 1 98 do hereby st	ate that under	4 - 7 - 8	<u> </u>	io	i2-
requirements of P.A. 74, Michigan conformance with regulations and r	PA ntissuu med	omer boints ment	JUNEO II MIRES I GIM & C	POLC MOVE III	5		 	++-
United States Department of the In	terior Bureau of Lan	id Management or	by a decree of a Court of	or Law and /or	6 -18 -17	161	514-	13-
that the corner points mentioned in Board of Land Surveyors or by	n lines 3, 4 and 5 abo a Decree of a Cou	ove were in confor int of Law: establ	mance with the rules of ished, re-established, :	nonumented,	7	 	 	 -
recovered, found as expressed belo)W:		,		8 -19-20-	212	2223-	24
NOTE: Not more than 2 come	one off in the same	town and range	may be recorded		9		 	+
on this certificate.	is, and the service	communication (gas,			10 30 29-	282	2726-	2′5
					11-0-			
					12 31 32	33	3435-	3 6
					13			
A. Description of original mon	ument and acces	sories and/or su	ıbsequent restoratior	1:				
evidence for this c	orner has been de (Book 1) by Davi ." Set 1" pipe, 4"	estroyed by cou id B. Babbitt R ' aluminum cap	lock, 14" - N60°E - mty road improvem LS No. 21558 states b. TIES: 4" H. Ma - S84°W - 40.70'.	CIUS. - "Sat in lin	e with very old fen	ce west an	d in the c	/l of
B. Description of corner evid	ence found and/o	r method applie	d in restoring or rees	tablishing co	rner:	4 D W la (a		
We found a 1 inch diamete part "C") in a location as it North - South County Road	ndicated in Land	Corner Record	ine running West	nd fits well	with measurement	s to corner	s 1/2 mile	e
North - South County Road East and 1/2 mile West. W	/e accepted the ex	xisting monum	ent as the best avai	aute cylactic	or the position o			
•							erii XXII XXX	.
							OF MIC	Wales
C. Description of monument						°	WILDIAM	A B
Accepted existing 1" dia. I	ron Pipe/4" dia.	Aluminum cap				* *	Lenca Land Surveyor	索
5" dia. Ironwood	N75°E	41.43 feet	"X" cut in upper	& lower bla	izes		€a. 26461	8
8" dia, H. Maple	S410E	69.08 feet	Ex. B.T.	•		Face .		IN FAIR
9" dia. H. Maple	S490W	51,24 feet 41,22 feet	Ex. B.T. Ex. B.T.			VE CO	EO LAND	Sec. May
10" dia. Twin H. Mapl Metal Survey Sign Pos		27.0 feet	Ex. D.1.					Pwier
NOTE: All bearings are a	nagnetic bearing	s. All distance	s are measured with	a steel tape.	Distances to trees	are to nail	in side of	f tree.
Signed by William	y Jula			Date	Dec. 29, 1998			<u></u>
Surveyor's Michigan License	, ,	61						
Sarroj de Simbingan Essendo			•					

727