LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Approved by	Menominee	County
Land Survey	Remonume	ntation
Peer Group		

i aci diarch cisade NPC (NPC (NP		
P.A. Of 1990 On	12/14	_1998
M	Marie	21-
100	HACIÍ 1	225
•	Chairman	

For corners in	1
MENOMINEE Located In: Corner Code #	HERAGO IN
(County)	
1. Public Land Survey T37N R 27W T R T R T R	RECUIVED FOR RECORD 9 JAN 27 PM 1: (9
2. Property Controlling in Section STR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	- ABCDEFGHIJKL
(SAME AS CORNER G-01, T36N - R27W)	2 6 5 4 3 2 1 1 1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
I, <u>William Lenca</u> , in a field survey on <u>Aug. 17</u> , 19 <u>98</u> do hereby starequirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 a conformance with regulations and rules therefore as required in the current manual of survey instruunited States Department of the Interior, Bureau of Land Management or by a decree of a Court of that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, in recovered, found as expressed below:	te that under 4 7 8 9 10 11 12- bove were in sections of the f Law and /or 6 18 17 16 15 14 13- the Michigan
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25
	11
	$12 \begin{array}{c ccccccccccccccccccccccccccccccccccc$
A. Description of original monument and accessories and/or subsequent restoration	
 Original Survey by H. Brevoort, Jr. (Township Boundary) - B.T.'s - \$21 lks. All original evidence for this corner has been destroyed by Coriginal Survey by Francis Coleman (Sectional Subdivision) - B.T.'s - 29 lks. All original evidence for this corner has been destroyed by L.C.R.C. No. 305 by William Lenca, RLS No. 26461, states "Set constone & wire fence to the west. This position checks well with GLO B.P N60°E - 37.32'; 10" Elm - Scr NBT - \$16°E - 110.68'; PP - \$3.000 lb. P N60°E - 37.32'; 10" Elm - Scr NBT - \$16°E - 110.68'; PP - \$3.000 lb. P N60°E - 37.32'; 10" Elm - Scr NBT - \$16°E - 110.68'; PP - \$3.000 lb. 	county road improvements. 5 - Sugar, 12" - S26°E - 28 lks.; Hemlock, 9" - S54°W county road improvements. There in center of N-S Co. Rd. and in line with ancient ties N-S-W." Set 3/4" x 18" Iron Pipe: Fc Post - Scr. 38°W - 60.89'.
B. Description of corner evidence found and/or method applied in restoring or reest	ablishing corner:
We recovered a 3/4" x 18" Iron Pipe in the centerline of a North - South Coufence to the West per L.C.R.C. No. 305. We also recovered the Elm B.T. and corner falls 12' North of a County Road centerline to the East. This position 17 years, and is accepted as the best available evidence of the position of the	has been consistently used by local surveyors for at least
C. Description of monument for corner and accessories established to perpetuate lo	cating the position of the corner:
Set 2" dia, Aluminum Pipe 30" long/3-1/4" dia. Alum cap stamped for corne	
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" Metal Survey Sign Post	N48°E 33.55 feet 1' N. of Road Sign S36°E 56.15 feet 1' W. of Fence Post S39°W 60.09 feet 1' E. of P.P. N75°W 25.22 feet @ Sign Post N75°W 26.1 feet
NOTE: All bearings are magnetic bearings. All distances are measured wi	th steel tape. Distances to trees are to nail in side of tree.
Signed by 10) Main Frica	Date Aug. 25, 1998
Surveyor's Michigan License No	

756