## SURVEY & REMONUMENTATION

APR 2 4 1995

## COMMISSION

Approved by Menominee County Land Survey Remonumentation Feer Group Under Act 345 Of

PA 01 1990 On 22. 9, 199 24.

(Chairman Janua)

## LAND CORNER RECORDATION CERTIFICATE

<b>5</b>	Filing Req	uirement of Act 74, Mich. P.A. 19	170							
For corners in MENOMINEE	Located In:	Corner Code ≠≠		75	27.07.07.02.07.02.02.02.02.02.02.02.02.02.02.02.02.02.	<del>1</del> <del>1</del> <del>1</del> <del>1</del>	? ?	7 1		
1. Public Land Survey	T <u>39 N</u> R 25 W T R T R			) #5 	RBARA MOR	/	YED FUR	9		
2. Property Controlling in Section	S T R S T R			\$6858 8585 8585	RRISON	かった			٠.	
<ol><li>Miscellaneous Property in Sec.</li></ol>	S T R S T R		Register	of Dec	eds St	amp<8	File	Numl	ber	<u>_</u>
Lot No      Private Claims		SW COR. SEC 10]	2 2	B C	D E	F C	3	2-	κι	. M
I, M.P. DAVIS	, in a field survey on rrequirements of P.A. 74. Michigan	OCTOBER , 19 94 , P.A. of 1970, the corner points mentioned	4 5 6	-		_9_	_10		-	12_
in lines 1 and 2 above we current manual of survey in Management or by a decrea above were in conformance	re in conformance with regulations nstructions of the United States De e of a Court of Law and/or that the co e with the rules of the Michigan Boa	s and rules therefore as required in the partment of the Interior, Bureau of Land orner points mentioned in lines 3, 4 and 5 and of Land Surveyors or by a Decree of a re-monumented, recovered, found as	7 8 9	19	-20	-21		23-		24
NOTE: Not more than on this certification	4 corners, all in the same town ate.	n and range, may be recorded	11 12	31	-32	-33	<del> </del> 34	-35-		36
G-4 [W1/4 COR S.10] (	nal monument and accessories G. ADAIR D.S 1852 - WOOD POS CE OF SUBSEQUENT CORNER RECOVER!	and/or subsequent restoration: T (SUGAR 14"-N47°N-0.29 CRAINS) (BEE Y OR MONUMENTATION.	CH 07"-574	°E-0.1	1 CHAI	NS)		<b></b>		
G-5 [SW COR 5.10] G.	. ADAIR D.S1852-WOOD POST (SU	GAR 16"-N66"E-0.14 CHAINS) (BEECH 15	'-587'W-0.	20 CHA	INS)			٠		

- 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- G-4 [WI/4 COR S.10] FOUND IN PLACE A 1" SOLID IRON (AXLE SHAFT) IN APPROX C/L OF CO. RD. NORTH & IN LINE WITH ANCIENT FARM FENCE LINES E. & W. THIS NONUMENT PLACED BY PERSONS UNKNOWN. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE POSITION OF THE ORIGINAL CORNER.

NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY OR MONUMENTATION.

G-5 [SW COR S.10] NO EVIDENCE OF ORIGINALS FOUND - RESET CORNER AT JUNCTION OF FENCE LINES N,S, & W. (NOW DOWN AND IN POOR CONDITION) ACCEPTED THIS LOCATION AS BEST AVAILABLE EVIDENCE AS TO THE POSITION OF THE ORIGINAL CORNER.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 6-4 SET OVER EXISTING MONUMENT A BERNTSEN AIMB30 ALUMN MONUMENT WITH THE CAP STAMPED TO ID THE CORNER POSITION.

POWER POLE

FIRE NO. SIGN POST N30°W SURVEY MONUMENT SIGN POST

CORNER FENCE POST S84°E

N79'W 35.35'(TO FACE)

24.30'(TO FACE)

S63'E 19.17' (TO FACE)

28.80' (TO FACE)

G-5 SET A BERNTSEN AINB30 ALUMN MONUMENT WITH THE CAP STAMPED TO ID THE CORNER POSITION.

BASSWOOD 10"

IRONWOOD 6\*
N14°W

MAPLE 6" N72"E SURVEY MONUMENT SIGH POST

\$70'W

20.52'

12.35

\$24°E 3.77' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT, UNLESS OTHERWISE NOTED.

Signed by M.P. SAUL

Date 12/9/94