SURVEY & REMONUMENTATION

Surveyor's Michigan License No. 16926

Approved by Menominee County Land Survey Remonumentation Peer Group Under Act 345 Of

Peer Group Under Act 345 Of P.A. Of 1990 On ________ 9 APR 2 4 1995 LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970 For corners in MENOMINEE Located In: Corner Code ## (County) **Public Land Survey** T 39 N R 25 W __ R __ R **Property Controlling** S т R in Section Т _ R Miscellaneous S Т R Register of Deeds Stamp & File Number Property in Sec. Т _ , Recorded Plat . Private Claims I-3 [NE COR SEC 10] J-3 [N1/4 COR SEC 11] 3 OCTOBER . in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 Description of original monument and accessories and/or subsequent restoration: I-3 [NE COR S.10] G. ADAIR B.S. - 1852 - WOOD POST (CEDAR 10"-S70"W-0.11 CHAINS) (HEMLOCK 18"-N81"E-0.11 CHAINS) NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY OR MONUMENTATION. J-3 [N1/4 COR S.11] G. ADAIR D.S.- 1852 - WOOD POST (WHITE PINE 08"-N44-1/2"W-0.22 CHAINS) (CEDAR 12"-S54-1/2"E-0.10 CHAINS) M. S. MCNABB - 1941 - IN PLACE - NO WITNESSES NOTED OR DESCRIPTION OF MONUMENT GIVEN. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: MIC I-3 [NE COR S.10] NO CORNER EVIDENCE FOUND AS ALL EVIDENCE OF CORNER POSITION APPEARS TO HAVE BEEN DESTROYED DURING ROAD CONSTRUCTION. REESTABLISHED CORNER POSITION AT C/L INTERSECTION Þ OF COUNTY ROADS N, S, E, & W. ACCEPTED THIS LOCATION AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE POSITION OF THE ORIGINAL CORNER. M. P. DAVIS LAND SURVEYOR NO. J-3 [N1/4 COR S.11] NO CORNER EVIDENCE FOUND AS ALL EVIDENCE OF CORNER POSITION APPEARS TO HAVE BEEN 16926 DESTROYED DURING ROAD CONSTRUCTION. FOUND M. S. MCNABE'S (DELTA COUNTY SURVEYOR) 1936 E1/16 AND HIS 1941 NE CORNER OF SEC. 11. EXTENDED LINE WEST FROM SECTION CORNER THRU E1/16 CORNER PED LAND AND RESET 1/4 CORNER ON THIS LINE AT A DISTANCE WEST OF THE E1/16 CORNER THAT IS EQUAL TO THE DISTANCE FROM THE SECTION CORNER TO THE E1/16 CORNER. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: I-3 SET INSIDE A MON BOX A 5/8" X 18" REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE CORNER POSITION. POWER POLE SURVEY MONUMENT SIGN POST BALSAM 5* POWER POLE N37°W \$58'W N49°E S57°E 48.47' (TO FACE) 42.16' (TO FACE) 74.641 46.58' (TO FACE) J-3 SET INSIDE A MON BOX A 5/8" X 18' REBAR W/A 3-1/4" ALUMN CAP STAMPED TO ID THE CORNER POSTION. SURVEY MONUMENT SIGN POST CEDAR 4° CEDAR 12" \$10°W \$54°E NORTH 32.691 17.50' (TO FACE) NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT, UNLESS OTHERWISE NOTED. Signed by _ Date __