## SURVEY & REMONUMENTATION

## JAN 092001

## SECTION

, Recorded Plat

4. Lot No. 5. Private Claims

recovered, found as expressed below:

## LAND CORNER RECORDATION CERTIFICATE

White act no menounines contito
Land Survey Remonumentation
Peer Group Under Act 345 of
PA. Of 1990.On /2/22 2000
Mechanis Zis

	Peer Group	Under A	ct 345 ·	of
A.	Of 1990,On.	12/2	乙 20	00
		A30		
	Ct	iairman	•	

For corners in MENOMINEE	Filing Requirement of Act 74, Mich. P.A.	Chairman
(County)	Located In: Corner Code #	BR.6 Pg. 223
1. Public Land Survey	TR	RECEIVED FOR RECORD 28 DEC 2000 2:31:31 PM
Property Controlling     in Section     Miscellaneous     Property in Sec.	S TR	BARBARA MORRISON REGISTER OF DEEDS MENOMINEE, MI 49858
		Register of Deeds Stamp & File Number

7 D	~ n				
1 A B	C D	E F	G H	1 J	K L
2 - 6-	- <del>  </del> -	<del>                                     </del>	<u> </u>	<u> </u>	<u> </u>
3			<del>                                     </del>		<u> </u>
4 - 7 -	<del> </del>		  10	11-	12-
5	<del>  </del>	<del>                                     </del>	$\vdash$		
6 -18-	-17-	15-	15-	  14	13
7	+-	<del> </del>			
8 — 19—	20_	21	_22	23	24
9					
10—30—	  29	28	27 <b>6</b>	26-	25
11					
1231	32	33	34	35	<u></u> 36
13					ļ

William Lença 19 00 Aug. 14 in a field survey on do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
  - Original Survey by George E. Adair B.T.'s Cedar, 13" N77°W 0.10 chs.; Hemlock, 10" S57°E 0.31 chs. All 1848: original evidence for this corner has been destroyed by county road improvements.
  - Private records of M.P. Davis, RLS No. 16926, indicate that a P.K. Nail was found in the centerline of a North South 1993: County Road and in line with a fence running West. The P.K. was replaced with an Iron Pin.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 5/8 inch x 8 inch iron rod in the centerline of a North - South County Road and in line with an old fence running West. Measuring North from this corner we find an old fence running West at a distance of 1319.5 feet and the center of a county road intersection at a distance of 2640.5 feet. This corner has been used by local surveyors for several years, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER" 5" dia. Cedar 4" dia. Cedar Metal Survey Sign Post Nothing else nearby	N90 <sup>o</sup> E S47 <sup>o</sup> W N51 <sup>o</sup> W N90 <sup>o</sup> E	32.55 feet 51.11 feet 44.75 feet 32.95 feet	Scr. NBT Scr. NBT
--	--	--	----------------------

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

$\mathcal{L} \cap \mathcal{L}$		
Signed by 1 Man Ence	Date	Aug. 19, 2000
	Date	
Surveyor's Michigan License No. 26461		

B FRACA