JAN 1 9 2000

Surveyor's Michigan License No. 33977

LAND CORNER RECORDATION CERTIFICATE

For corners in SECTION			TION	Filing Requirement of Act 74, Mich. P.A. 1970			#1355		
Missaukee County				Located In:	Corner Code #		MISSAUKEE COUNTY MICH	HIGAN	
1. [Public La	and Surv	ey	T 21N R_06W T R T R	M-11		Carolyn Flare		
2. Property Controlling S			S S	TR TR TR TR TR			Register of Deeds Stamp & File Number		
4.	Lot No.		, Recorded	Plat			A B C D E F G F I	т к т. 1	
5. Private Claims							2 6 5 4 3		
required inst deci	irements e in confoructions of a Conformance	of P.A. 74 ormance wo of the Unit Court of Lar with the I	 Michigan P.A. ith regulations a ed States Depa and /or that trules of the Mic 	eld survey on <u>June</u> , of 1970, the corner poin of rules therefore as requ intrinent of the Interior, B he corner points mention thigan Board of Land Sur mented, recovered, found	nts mentioned in lines 1 a uired in the current manu cureau of Land Managem aed in lines 3, 4 and 5 ab veyors or by a Decree of	ind 2 above al of survey ent or by a ove were in	4 7 8 9 10 15 15 15 16 15 17 16 15 17 16 17 16 17 17 16 17 17 16 17 17 16 17 17 17 17 17 17 17 17 17 17 17 17 17	-1413 -23	
NO.		more than this certifi		n the same town and ran	ige, may be recorded		11	35 36-	
A.	Descrip	tion of or	iginal monume	ent and accessories an	d/or subsequent resto	ration:	13		
	 M-11) 1837 GLO Section Corner Post by John Brink, Deputy Surveyor. 13" Yellow Pine-S19W-16 lks, 14" Yellow Pine-N74W-15 lks. M-11) 1852 GLO Section Corner Post recovered by A. Curtis, Deputy Surveyor. 14" Y. Pine-N65E-44 lks, 14" Y. Pine-S28E-45 lks. M-11) 1938 Schaaf notes; Found post. Set monument. M-11) 1987 Roser survey and LCRC; Liber 1, Page 730; Found 1½" pipe set by Schaaf from USBT stumps, added Cedawith location tag. 19" Oak-S30E-55.8', 21" Oak-S20W-58.5', 26" Oak-N50W-18.5', 9" Oak-N70E-5.3'. 							Cedar post	
В.	Description of corner evidence found and/or method applied in restoring or reestablishing corner:								
	M-11) Section corner common to Section 25, T21N, R6W, Section 36, T21N, R6W, Section 30, T21N, R5W, and Section T21N, R5W. Found 1½" pipe and cedar location post as recorded in Liber 1, Page 730. This corner is accepted as careful and faithful perpetuation of the position of the original corner. Possible GLO witness: S25W 10.7' Face of ±15" old stump.							ection 31, ed as a	
c.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:								
	M-11) Found 1½" pipe and drove 5/8" x 36" rebar into pipe and set Missaukee Co					saukee Coun	ty Monument.		
		N22W \$78W \$75E \$20W *N48W *N63E *S26W	21.72' 18.23' 5.65' 60.60' 19.0' 5.2' 58.5'	Set nail in north face Set nail in south face Set nail in east face 30" oak deadfall	e of 6" white pine of 16" twin oak	mp			
		*Previous Witness		8" oak deadfall 18" oak with blaze (dead) OF MICHOLA GEERS PROFESSIONAL SURVEYOR No. 33977 PAGESSIONAL Date		<u> </u>	Peer Group Reviewed and Approved Date: 72,99 J. Dsan Geers, Missaukee Co. Representative		
Sic	ned by		70-	Or A THE WAY	GEERS OFESSIONAL OFESSIONAL No. 33977 OFESSIONAL OFESSIONAL OFESSIONAL OFESSIONAL OFESSIONAL OFFESSIONAL OFFESS	Date	J. Dean Geers, Missaukee Co. Represen	IIGH¥6	
_	, , -	Michigan	License No. 3	1430	KXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	<u> </u>			