REMONUMENTATION

LIBER <u>291</u> PAGE <u>419</u>

APR 9 4 1005

Surveyor's Michigan License No. ___33977

969

APR & 4 1993 BAILD COMMEN RECONDATION CENTIFICATE				
For com		Filing Require	ement of Act 74, Mich. I	P.A. 1970
<u>Missa</u>	aukee (County)	Located In:	Corner Code ##	MISSAUKEE COUNTY MICHIGAN
1. Publ	ic Land Survey	T <u>22N</u> R <u>8W</u> T R T R	M-11	RECORDED INAN 2 3 1995 / A.M.
in Se	ection Sellaneous	S T R S T R S T R		Register of Deeds Stamp & File Number
		orded Plat		
1, <u>J. Dean Geers</u> , in a field survey on <u>November</u> , 19 94. do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as				
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			30-1129-20-27-20	
A. Desc	cription of original mor	ument and accessories and	l/or subsequent restoration	13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
N N	M-11) 1837 GLO post by John Brink, Deputy Surveyor, Black Ash 12 N 36° W 58, Black Ash 13 S 33 1/2° W 42 M-11) 1894 Beuthien survey: Cedar stake and stone; West end culvert S 35° W 32.7° M-11) 1911 Beuthien survey: Cedar stake and stone; West end culvert N 44° W 51 M-11) 1966 MDOT LCRC, Liber 1, page 235: Found 3/4" pipe, raised with 5/8" lag bolt, corner fits 1920, 1935 & 1938 MDOT survey notes M-11) 1976 McClung LCRC, Liber 1, page 515: Found 1" Iron in monument box (continued on back) Description of corner evidence found and/or method applied in restoring or reestablishing corner:			
N	4-11 Section corner	common to Sections 25	& 36, T22N, R8W and	Sections 30 & 31, T22N, R7W
Found 1" Iron in monument box recorded in Liber 1, page 515. Corner is in center of intersection. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.				
C. Desc	ription of monument fo	or corner and accessories e	stablished to perpetuate k	ocating the position of the corner:
M-11) Set 2 1/2" brass Missaukee County monument on 1/2" Iron in monument box				
	N 48° E - 10° S 44°E - 58.9	1.02 - Found nail in power 1.77 - Top center of steel 0 - Found nail in power p 1.94 - Set Iron and cap	guard post	Peer Group Reviewed and Approved Date: 12-7-94
				J. Dean Geers, Missaukee Co. Representative

_ Date ___12/15/94