
LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Missaukee		Located In		Corner Code #
(County)				
1. Public Land Survey		T	_ R R	
Property Controlling in Section	S 19	T 23N	R 7W	4
3. Miscellaneous Property in Section	S 19 S	T 23N	R_7W R R	8
4. Lot No:	Recorded Plat:			
5. Private Claims: _				

Register of Deeds Stamp & File Number



I, <u>Craig W. McVean</u>, in a field survey on <u>Dec. 16</u>, 20<u>09</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- 4 1892 1914 CSR FB #35, p. 55 E. A. Beuthien 1) B. Oak 6" S65°E 91 2) B. Oak 5" N75°E 86
 - 1974 Record Survey L. S-1, p. 177 J. L. Wilcox Shows calc. position for corner. Doesn't show iron set.
- 8 1892 1914 CSR FB #35, p. 55 E. A. Beuthien Petition Survey Sec. 19.
 - 1) WPS 44 S9°E 48
 - 1974 Record Survey L. S-1, p. 177 J. L. Wilcox Shows calc. position for corner. Doesn't show iron set.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- $\underline{4}$ NW 1/16 Corner Sec. 19 Fd. $\frac{1}{2}$ " x 24" long smooth iron with cap #14102 per Wilcox. Could find no evidence of Beuthien witness or old occupation. Wilcox iron fits proper subdivision of section and is accepted as the best available evidence of the position of the corner.
- 8 CW 1/16 Corner Sec. 19 Fd. ½" x 24" iron with cap #14102 per Wilcox. Fits proper subdivion position within reason. 27' East of 1/2" CIR found old fence corner remains S & E. A 40"± WPS is S9°E 31.6' to face from the apparent fence corner. Dug at fence corner looking for stake but nothing conclusive. Area looked like it had been dug before. This fence corner is probably Beuthien's position but it is way out of position from his dimensions and proper subdivision position. Thus, I felt that the Wilcox position was the best position though it is not the most historical position. Some of Beuthien's positions in this section have been poorly placed. Some we have accepted and some we have not. 1/2" CIR #14102 accepted as the best available evidence of the position of the corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 4 Replaced 1/2" x 24" CIR #14102 with stamped 2" Alum. Cap on $5/8" \times 34"$ iron rebar. Set Blue Carsonite Post with loc. tag 1' N. NW 0.4' to fd. steel fence post - Up 2' S72°W 18.35' to set N & T in S. side 25" Oak N24°E 23.87' to set N & T in E. side Tw. 11" Oak S86°E 74.59' to set N & T in N, side 14" W. Pine S7°W 47.66' to set N & T in E. side 17" Oak
- 8 Replaced 1/2" x 24" CIR #14102 with stamped 2" Alum. Cap on 5/8" x 34" rebar. Set Blue Carsonite Post with loc. tag 1' NW. Reset steel fence post 1' SW S27°E 6.03' to set N & T in E. side 14" R. Maple S51°E 30.60' to set N & T in SE side 13" R. Maple N56°W 45.29' to set N & T in SW side 15" Oak S5°W 51.17' to set N & T in W. side Tw. 17" Oak

Surveyor's Michigan License No.: 39088

Date:

OF MICHIGA CRAIG W. MCVEAN PROFESSIONA SURVEYOR 39u 39u 39u Reviser Reviser Rev

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSION AN: 28, 1971

Revised May 14, 1975 Revised Jan. 1983 Revised Oct. 1995