

MAY 28 1997

## LIBER 308 PAGE 692

## LAND CORNER RECORDATION CERTIFICATE

COMMISSIONFiling Requirement of Act 74, Mich. P.A. 1970

# 1061

Missa	ükee	Located In:	Corner Code #	, ,00/
	(County)	•		MISSAUKEE COUNTY MICHIGAN
1. Public La	and Survey	T 24N R 6W	G-7	
		<u>T</u> R	<del></del> . (	RECORDED [DEC 2 0 1996 Am.
		T R T R	<del></del>	Carolyn Flore
2. Property	Controllina S	TR		( ) de de la constante de la c
in Section		TR		acoust Frank
3. Miscella		TR		Register of Deeds Stamp & File Number
Property	in Section S	T R	<u> </u>	negister of beads stamp & File Number
4. Lot No.	. Recor	ded Plat		
5. Private C	laims			A B C D E F G H J K L
				2
				<u>"                                    </u>
, J. Dea	n Geers in a	field curvey on Opcom	her 10.94	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned				
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land				
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  8 19 -20 -21 -22 -23 -24				
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a				
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				
NOTE: Not more than 4 corners, all in the same town and range, may be recorded				
	nis certificate.		<u> </u>	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:				
G-7)	GLO Section post	by Whelphiey; Beech 15-S7	9W-24, Beech 12-N78W-4	7, Sugar 15-N67E-29
G-7)	1972 Ostling LCRC, Liber 1, Page 51; Found boat spike, pk. in PP-N63E-60.8, pk. in PP-N70W-90.9, pk. in 22"			
	Maple-S42E-65.9			
G-7)	1973 Radeliffe LCRC; Liber 1, Page 164; found 1/2" rod, TP-N80W-90.82, PP-S05W-43.51, TP-N75E-60.71			
G-7)	1978 Granger Survey, Liber 5-3, Page 394; Found 1/2" rod, TP-N80W-90.82, PP-S05W-43.51, TP-N75E-60.71			
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
		·		
G-7)				
	West centerline and in centerline of North-South Road. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.			
	perpetuation of the	e position of the original con	na,	
•				
	•			
-			•	
C. Descrip	tion of monument fo	or comer and accessories of	established to perpetuate le	ocating the position of the corner:
G-7)	Set Missaukee Co	unty Mon. on existing Iron		
	S54E - 63.52			
		- 4" White Pine 3 - 12" Scotch Pine		Poor Croup Devisored
		- Telephone Pole		Peer Group Reviewed and Approved
		7.7.20		Date: (2-12-96
	OF MICH			J. Dean Geers, Missaukee Co. Representative
	- Lancer	(1) The state of t		
Signed by			Date_	12-19-96
Surveyor's Michigan License No. 13977 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983				
		or Strate		netices and, 1903