REMONUMENTATION

(

DEC 07 1994

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corner		MESILIN			I	LEOOALEZE	- 00 UN (T) / 1	40.00
	Missa	(County)	Loc	ated In:	Corner Code -##		MISSAUKE	E COUNTY N	MICHIGAN , , 5
1.	Public	Land Survey	Ť	24N _R 7W R	D-9		PECORDED ()(CT 2 8 199	4 /p M
2.	Proper in Sect	ty Controlling	T S T	RR			Caroly	n F	lare HEGISTER
3.	Miscell		S T	R R		Register of Deeds Stamp & File Number			
I. John Ma abor ext	J. De hereby ce ines 1 ar rent man nagemen ove were surt of La oressed botte: No	ean Geers ertify that under re nd 2 above were i ual of survey instrictor by a decree of in conformance wi aw; established, below: but more than 4 of this certificate. ption of original	in a field sur quirements of P in conformance uctions of the U a Court of Lawar th the rules of the re-established. corners, all in the monument and Quarter Section	vey onJuly_A 74, Michigan P A with regulations an inted States Depared or that the corner Michigan Board of monumented, restate same town and accessories and on post by Wh 20 S 9 1/2 E 2	of 1970, the corner point of rules therefore as required points mentioned in line of Land Surveyors or by a monumented, recovered and range, may be record/or subsequent restored the land surveyors of the land surveyors of the land surveyors or by a monumented, recovered and range, may be recorded as land to the land surveyors.	s mentioned pured in the reau of Land es 3, 4 and 5 in Decree of a direction for the control of	A B C D 2 6 5 5 6 7 8 7 7 8 9 10 30 29 11 12 31 32 13	F G H	13 K L M
	Hemlock 20 S 9 1/2 E 22, elm 26 N 72 W 23 D-9) 1909 Cavanaugh, County Surveyor: Gas pipe in concrete Sugar 16 S 16 3/4 W 61, Hemlock 30 S 60 3/4 E 132 D-9) 1978 Mears Engineering, S-1, page 460: Set corner single proportion between section corners D-9) 1981 Roser, Liber 1, page 628: Found Iron as set by Flaherty and recorded at S-1, page 460								
В.	Descri	ption of corner e	evidence found	i and/or method	applied in restoring o	r reestablishing	corner:		
	D-9)	Four	nd 1/2" Iron faithful re-es	to Sections 20 as recorded in tablishment of est road Center	Liber 1, page 628 the position of the	. This corner original corn	is accepted as er. Corner is	s a careful ±3.5'	
C.	Descri	ntion of monum	ent for corner	and accessories	established to perpet	uate locating th	e position of the	corner:	
J .	D-9)	Set 1/2" Iro	n and Missa		nonument in monument in monume		d and Approved	OF ANOMATICS AND SURVEYOR	
e:-	ned by	01			D:		A Common of the	SEO LAND SUP	S. A. S.
_		Michigan Licen	se No. 3397				OVED BY MICHIGAN STATE	SOARD OF LAND SUR	EYORS, JAN. 28, 19
	•						•		REVISED MAY 14, 19 REVISED JAN., 19