SUAVEY & REMONUMENTATION

MAY 2 8 1997

LIBER 308 PAGE 681

COMMANS LAND CORNER RECORDATION CERTIFICATE

For corners	in.	A 1 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		Requirem	ent of Act 74, i	Mich. P.A. 19	⁷⁰ # 1050
For corners in Missauk		Loca	ited in:		Corner Code	• # .!	
							MISSAUKEE COUNTY MICHIGAN_
1. Public La	and Survey	•	Γ	R <u>7W</u> R R	<u>H-7</u>		RECORDED IDEC 20 1996 The M. Carolyn Flore
	.			R			01 400
2. Property in Section	_	s			****	}	awaye Flore
3. Miscellar		s s					REGISTER
	in Section	s		,			Register of Deeds Stamp & File Number
4. Lot No.	F	Recorded Plat					
5. Private C	laims						A B C D E F G H I J K
							2 -
							3
				0 4			4 - 7 8 9 10 11
1, <u>J. Dean Geers</u> , in a field survey on <u>December</u> , 19 96, od hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned							
In lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current							
manual of su	rvey instructions	s of the Unite	d States	s Department	of the Interior, E	Bureau of Land	7
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a							B 19 20 21 22 23 23
					re-monumented, r		9
as expressed					, , , , , , , , , , , , , , , , , , , ,	000,000,000,000,00	10 30 29 28 27 26
NOTE: Not	more than 4 co	mers, all in th	e same	town and rar	nge, may be reco	rded	11
	is certificate.						12 31 32 33 34 34 35
	tion of original	monument a	nd acce	ssories and/	or subsequent re	estoration:	13
H-7) H-7) H-7)	1892 Beuthie	n Survey in S	ection 15	5, T24N, R7V	V; corner was use	d but no witness	#W-23, Sugar 8-N38 3/4W-30 ses recorded i-N48W-88, Beech 5, N70½E-
H-7)	1979 DNR LC N-25.9, Corne	CRC, Liber 1, I er fits 1909 C	Page 633; avanagh	Replaced old witness Beed	l Iron with 5/8"x36 th (stump)-N70½	5" rerod, P.PS1 E-115	10E-92.15, St. Fence Post -due
B. Descript	ion of comer e	vidence four	nd and/o	er method ap	plied in restoring	g or reestablish	ning comer:
H-7)	Quarter Section as recorded.	n corner comn This corner is	non to Se accepted	ctions 15 and d as a careful	12, T24N, R7W. and faithful perpe	Found Iron and etuation of the po	d Cap in centerline intersection osition of the original corner
	ion of monume	ent for cornel	and ac	cessories es	tablished to perp	petuate locating	g the position of the comer:
H-7)	S7E - 90	4.98' - Teleph).69' - Teleph	one Pole one Pole	•			
•		60.22' - Set w					
	N 60W ·	· 91.09' - Set	wit. Iron	ın Çenterline	Driveway		eer Group Reviewed and Approved
	A CONTRACTOR	F MICH	•				000
	A STATE OF THE PARTY OF THE PAR	DEAN	b			J.	Dean Geers, Missaukee Co. Representative

Surveyor's Michigan License No. 33

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1911 REVISED MAY 14, 1915 REVISED JAN., 1963

Signed by_