## LAND CORNER RECORDATION CERTIFICATE

ř.	Filing Re	equirement of Act 74, Mi	IICN. PA 1970 		
For Corners In: Missaukee (County)	Located In	Corner Code #			
Public Land Survey	T <u>24N</u> R <u>8</u> T R	8W K2			
Property Controlling in Section	S T R S				
Miscellaneous     Property in Section			Register of Deeds Stamp & File Number		
4. Lot No:	Recorded Plat:				
5. Private Claims:		A B C D E F G H I J K L M			
I, <u>Craig W. McVean</u> , in a field survey on <u>April 15</u> , 2004 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Burcau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			3 4 7 8 91011 12 5 181716151413 7 8 192021222324 9		
NOTE: Not more than be recorded on this ce	2 corners, all in the same to rtificate.	own and range, may	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36		
A. Description of original monument and accessories and/or subsequent restoration:					
K2 - GLO - Set ¼ post - T. Whelpley - 1853       LCRC #689 - R. F. Mitchell - 1983         Beech 4" N68½°W 10 L.       Fd. 1" iron pipe         Nor. Pine 13" N61°E 55 L.       6" Oak S30°W 21.90'         DNR Cor. Rec. and LCRC #329 - K.J. Ostling - 1967       4" Oak S68°W 8.35'         Set 1" pipe w/ 4" Alum. Cap by Prop. meas.       10" R. Oak East 23.45'         between Sec. Cor No original evidence       4" Oak N10°E 11.97         7" R. Oak S86°E 23 L.       4" Oak N10°E 11.97					
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:					
K2 – ¼ Cor. common to closely. 2-track is 1 original corner.	Sec. 1 & 2 – Fd. DOC (DNR) 0' S. Broken DOC (DNR) mo	broken alum, cap on 1" iro on, accepted as a careful a	ron pipe per Ostling and Mitchell. Fit SP position and faithful re-establishment of the position of the		
C. Description of monum	ent for corner and accessorie	es established to perpetuat	ate locating the position of the corner:		
K2 – Placed 3 ½" "State N10°E 11.96' to fd. S89°E 23.43' to se S70°W 37.36' to se S24°W 21.89" to fd. S62°W 8.38' to fd. Set blue carsonite Fd. Cedar post on	of Michigan" Alum. Cap on ex. nail in E. side 6" Oak (RFM) t N & T in N. side 16" R. Oak et N & T in SE side 21" R. Oal d. nail in E. side 7" R. Maple (R nail in SE side 7" R. Maple (R post 1' N.	xisting 1" iron pipe. scribed 'XBT' (KJO, RFM) k scribed 'XBT' (KJO) RFM)	AE OF MICHIO	LUNEYOR X	
Signed by: Wey 1. 1/16 Ven Date: 5/20/2004					
Surveyor's Michigan Licerse No.: 39088					