SURVEY & REMONUMENTATION

APR 2 4 1995

Montmorency County Remonumentation

Filing Requirement of Act 74, Mich. P.A. 1970

LAND CORNER RECORDATION CERTIFICATE iber 00012 Page 0127

For corners in

expressed below:

COMMISSION

	in the second se	
	Montmorency (County)	Located In: Corner Code ## Albert Township
1.	Public Land Survey	T 29 N R 1 E K-13 T 29 N R 1 E (1-13) T R
		T R APPROVED BY
2.	Property Controlling	S T RPEER GROUP
	in Section	S T R
3.	Miscellaneous	STRINV_1
	Property in Sec.	STR

STATE OF NICHIGAN MONTMORENCY COUNTY -Recorded % Filed

,	•	Τ	R			•		1	1-10	I-19	94 1	4:12	2: 14	}				
Property Control in Section									A. PANGAN-MCELROY REGISTER OF DEEDS									
Miscellaneous Property in Sec.	S _ S _	Registe	Register of Deeds Stamp & File Number															
4. Lot No	, Recorde	ed Plat					A B	C	D E	F	а н	i	J K	L	h			
	nder requireme were in confor y instructions cree of a Court,	nts of P.A. 74 mance with of the United of Law and/o	,MichiganP regulations I States Dep rthat the cor	and rules therelore artment of the Inte mer points mention	er points mentione e as required in th rior, Bureau of Lar ed in lines 3, 4 and	ed 6 he 7 nd 7		1	7	-16-			111		23			

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- (K-13) South Cor. common to Secs. 35 & 36, 7 29 N, R 1 E Post set by Lewis Clawson Dec. 1839. 8" 5pr. Pine N 24° W 40 links 20" J. Pine N 56° E 47 links

(L-13) S. ½ Cor. Sec. 36, T 29 N, R 1 E Post set by Lewis Clauson Dec. 1839. 6" Spr. Pine N 34° W 53 links

N. Caldwell - Survey - L. 1, P. 399.

6" Spr. Pine N 37° E 21 links

R.S. Scott Engineering - Survey - 1-18-1974.

R.S. Scott Engineering - Survey - 1-18-1974.

- R.S. Scott Engineering Survey L. 4, P. 83.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K-13) South Cor. common to Secs. 35 & 36, T 29 N, R 1 E Found 2" pipe in concrete base. N.W. Cor. Sec. 1, 28/1, 7.92' West.

(L-13) S. $\frac{1}{4}$ Cor. Sec. 36, T 29 N, R 1 ϵ Found 1" pipe & square Oak stake. N. 1 Cor. Sec. 1, 28/1, 4.71 West.

No evidence of original corner.

No evidence of original corner.

Accepted as the best available evidence of the reestablishment of the original corner.

Accepted as the best available evidence of the reestablishment of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (K-13) South Cor. common to Secs. 35 & 36, T 29 N, R 1 E Placed Remonumentation Cap in 2" pipe in concrete. 7" J. Pine 5 70° W 32.3' 15" J. Pine 5 30° W 29.58' 11" J. Pine S.1° W 30.78'

(L-13) S. 1/Cor. Sec. 36, T 29 N, R 1 E

Set concrete monument & placed Remonumentation Cap.

10" J. Pine N 21° E 26.12'

10" R. Pine N 89° E 33.74' 15" R. Pine S 23° E 49.27'

14" J. Pine S 3° W 32.63'

Witnesses marked with a 30 penny spike & I.D. tag #18660.

Donald & Marlat

12" Dak 5 89° E 69.2'

10" J. Pine N 9° W 42.4"

Date



Surveyor's Michigan License No. __

"Harman FORM APPROVED BY MICHIDAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971