l.iber <u>18</u> _Pago <u>_38</u>	}
-----------------------------------	---

Montmorency County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

		LAND COŔN	VER RECORDATION CERTIFI	CATE	*** E	<u> </u>	֟֟֞֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓	70	
Fo	r corners in	Filing Requi	irement of Act 74, Mich. P.A.	1970	TO THE	l, E		7	525
_			•		100	35			2
, M	YONTMORENCY	Located In:	Corner Code ##		30 000	¢		.:1	("7"
	(County)	RUST TWP.			PANGATING		<u>ت</u> س		11
1.	Public Land Survey	7 29N R 4E T 29N R 4E	A-12 A-13		ice (ja N	2		C
		TR			0		<u>ن</u> الم	50.	•
		T R							
2.	Property Controlling	S T R							
	in Section	S T R	· · · · · · · · · · · · · · · · · · ·						
3.	Miscellaneous	S R		Domintor of	D4- C		e.		
	Property in Sec.	S R		Register of	Deeds 3	uamp a	FIIE	Nume) @
4.	Lot No	, Recorded Plat							
				A B	U 0 1	FG	i H	I J	K T
	· 			2 - 6-	<u> </u>	_ i	_ _	<u> </u>	1
1				a	lil	i i	ĭ	ì	T
									十
	Enadoniob's Vina		at Cambaulau de	⁴ 	╼╂──₿╼╾╂	— ģ —	10	11-	十
المارا	horobused fulber	, in a field survey onAugu	st - september 19 93	5				 -	+
int	trereby certify that under	requirements of P.A. 74, Michigan P.A. in conformance with regulations a	A. of 1970, the corner points mentione	6 -18-	┴ ╎┤	_16	15	1-14-	1
		structions of the United States Department					_1_		1
,-			and the control of th	,~	1 7 7	7			

Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

A. Description of original monument and accessories and/or subsequent restoration:

A-12 West 1/4 Cor., Sec. 31, T.29 N., R.4 E. NO ACT 132 SURVEYS RECORDED FOR THIS CORNER NO ACT 74 RECORDED FOR THIS CORNER

A-13 S.W. Cor. Sec. 31, T.29 N., R.4 E. Orig. Post by Lewis Clason - Nov. 1839
N36W-17 lks(11.22')Pine, S36E-17 lks(11.22') Pine
NO ACT 132 SURVEYS RECORDED FOR THIS CORNER ACT 74 by N. Caldwell Rec. Bk. 1, Pg. 297 - June 1981 Fnd Rec 3" Pipe with Conc. N80E-32.3'-20" Pine, S75W-24.6'-Stone, S45W-26.35'-Pine Stmp, NORTH-0.5'-1%" Fnc Post S45E-1.0'-DNR Post, N15E-20.5'-18" Pine Stmp

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-12 West 1/4 Cor., Sec. 31, T.29 N., R.4 E. Fnd Rec 3" Pipe full of Conc. (Caldwell Wit) N.70°W. - 36.4' - Pine Stmp (Rec) (Rotted) N.15°W. - 6.9' - Pine Stmp (Rec) (Rotted) S.80°W. - 10.6' - Pine Stmp (Rec) (Rotted) NO ORIGINAL CORNER EVIDENCE FOUND

A-13 S.W. Cor. Sec. 31, T.29 N., R.4 E. Fnd Rec 3" Pipeefull of Conc. (Bk. 1, Pg. 297) S. 25°W. - 24°66 - Stone (Rec) NORTH -- 0.5' - 1%" Fnc Post (Rec) S. 45°E. - 1.0' - DNR Post (Rec) NO ORIGINAL CORNER EVIDENCE FOUND

Approved by Montmorency County Peer Review on Sept. 24. 1993, as a careful; and faithful re-establishment of the position of the corner.

Approved by Montmorency County Peer Review on Sept. 24, 1993, as the best available evidence of the original corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner.

-12	West 1/4 Cor., Sec. 31, T.29 N., R.4 E.
	Set Mont. Co. Re-Mon Cap, on 1/2" Iron, Along
	Side of Fnd. Pipe full of Conc.
	Corner is at Fnc Cor (Fnc to W & S)
	N.700E 22.12' - Set Tag S. Sd. 8" Maple
	S.650E 0.5' - Face of 14" Steel Fnc Cor Post
	S.250W 22.63' - Set Tag W. Sd. 12" Maple
	N.650W 68.29' - Set Tag NE Sd. 30" Maple
	Set Treated R.T. Post Along Side Corner

S.W. Cor., Sec. 31, T.29 N., R.4 E. Set Mont. Co. Re-Mon Cap in Fnd 3" Pipe Full of Conc. NORTH - 0.56' - S. Face of 1%" Steel Fnc Cor Post (Fnc to N & E) S.450E. - 1.00' - Cedar DNR R.T. Post S.45°E. - 9.53' - Set Tag SW Sd. 8" Maple S.65°W. -16.28' - Set Tag N. Sd. 10" Maple S.750W. -26.851(Rec As 24.61) Point on Stone OF MICHIGAN

NOTE: All Witnesses Marked with Dbl. Headed Nails & I.D. Tag #25852, unless otherwise note

Date Dec. 23 1994 ⊒ianed by

FREDERICK J. KING PROFESSIONAL SURVEYOR No. 25852

POFESSION

urveyor's Michigan License No.

TO THE TOTAL STATE OF STATE OF