For corners in

## REMONUMENTA Montmorency County Remonumentation

DEC 1 8 1995

Liber 00012 Page 0170

STATE OF MICHIGAN

MONTHORENCY COUNTY

## LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

MONTMORENCY		Located In:	Corner Code ##		Recorded & Filed	
	(County)	VIENNA TWP.			11-14-1995 10:17:34	
1.	Public Land Survey	T 30N R 1E	G-13		(Infantabh fhitiga	
		T R			A. PANGAN-MCELROY	
		T R T R		j	REGISTER OF DEEDS	
2	Property Controlling	S T R				
۷.	in Section	S T R				
3.	Miscellaneous	S T R		Register of Dee	ds Stamp & File Number	
	Property in Sec.	S T R				
		. I Disa				
		ecorded Plat			D E F G H I J K L M	
Э.	Private Claims			2 6 6	5-1-4-1-3-1-2-1-1-1	
			•	3		
				4 - 7-+-	8 1 9 10 10 1 1 1 1 2 1	
I,	Frederick J. King	, in a field survey on May 3.	, 19_95	ationed 5		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970; the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the						
current manual of survey instructions of the United States Department of the Interior, Bureau of Land						
Mai	Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a					
Cos	urt of Law; established, r	e-established, monumented, re-	monumented, recovered, for	und as		
,	pressed below:			10 30	29 - 28 - 27 - 26 - 25	
NO		orners, all in the same town a	nd range, may be recorde	d ''		
	on this certificate.			13		
Δ	Description of original	monument and accessories ar	d/or subsequent restoration		······································	
	13 - CORNER COMMON TO				1	
4-		nal Post set by Clason, Dep	uty Surveyor - N.210W.	- 23.10' (35 lks) - \	Pine	
	May 1039 - 011911	ial lost see by classing pop	N.30°E.	- 23.10' (35 1ks) - \	/ Pine	
		by. L. Beauregard, P.S.#1				
	States	s that 3" Monument Fnd, pos				
				50.20' - 6" Maple		
				68.10' -10" Oak	@ NW Cor., Sec.3, T29N-R1E	
	lung 1979 - Act 1	132 by L.G. Beauregard, P.S	.#18654. Rec. L.2. Pg.5	39 - States Rec. Cond		
В	Description of correct	viaence of the dangler method	applied in restoring or ree	stablishing corner:		
			<b></b>			
G-13 - CORNER COMMON TO SECTIONS 33 & 34  No Corner Found - Appears to have been removed by pipeline activity.						
	No corner round a	t Rec. 31.68' from Corner G	-1, T29N-R1E & on line	between Corners F-1_1	3 G-1, T29N-R1E	
	South - ± 67.9'	(R-68.10°) - Fnd Blaze in F	ec. 10" Oak (Now 18" Oa	k) Ar	PHOYED BY	
		(R-50.2°) - Fnd Blaze in Re		ple)	EER GROUP	
	East - 31.68' - 1	Found Rec. Axle Shaft @ Cor	ner G-1, T29N-R1E.		7135 G O OF	
					11N 0 2 95	
					SKIR	
					The state of the s	
	•					
		oved by Peer Review Committ	ee on June 2, 1995 as t	the best available ev	idence of the position	
	of the Original			Inaction the position of	f the corner:	
		ent for corner and accessories	established to perpetuate	locating the position o	The corner.	
G-	13 - CORNER COMMON TO					
	Set Conc. Mon &	County Re-Mon Cap @ 1/2" In	ron Location.	22 A01 . Cot Tag C	side 244 Manle	
	N.85°E. = 83.54°	- W face of Stop Sign Post Set Tag E side 18" Oak	N.75°W.	- 50.20' + Set Tag S	side 10" Maple	
	South = 00.30 =	West of West edge of N-S gi				
		.68' East of Corner G-13			OF MICE	
		d Stake alongside Corner G	-13	<b>ن</b>	The same of the sa	
				1	FREDERICK	
				₫.	A J. KING 【本集	
		1		<b>7</b>	PROFESSIONAL C SURVEYOR	
	. / ,	10 2	_	10-20-95	No. /##	
Sig	gned by <i>Fredoric</i>	l J. King	Date	10-30 99	25852	
Surveyor's Michigan License No. 25852 FORM APPROVED BY MICHIGAN STATE DATE OF LAND SURVEYING AM. 20, 1971						
	• •				BEAIRED THE THE	