## Montmorency County Remonumentation ber 00012 Page 0183

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970				
For corn	ers in		,	STATE OF MICHIGAN
	tmorency (County)	Located In:  AVFRY TWP.	Corner Code =## H-13	MONTMORENCY COUNTY Recorded & Filed
1. Publi	ic Land Survey	T 30N R 3E T R		11-21-1995 13:22:59
in Se	erty Controlling ection ellaneous erty in Sec.	T R T R S T R S T R S T R		A. PANGAN-MCELROY REGISTER OF DEEDS Register of Deeds Stamp & File Number
		Donat de de Dist		
		Recorded Plat		A B C D E F G H I J K L I
In Donald E. Marlatt, in a field survey on 4-24-1995  do hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:  NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.  A. Description of original monument and accessories and/or subsequent restoration:  (H-13) S. ¼ corner of Section 34, T 30 N, R 3 E.  Post set by Lewis Clason in 1840. N 9* E 10" Fir 1.09 links. N 5½* W 6" Cedar 1.15 links. Scott Engineering Survey on 6-13-1967. FOUND PIPE-NO WIT.  Norman Caldwell Survey on 1-15-1968. FOUND POST WITH PIPE-SET ½"BAR & CAP(WIT.SOUTH 2.11 Act 74 by Ted Miller on 6-25-1972, Recorded L. 1, P. 3. 12"BALSAM-SOUTH 35.31"P. POLE.)  Survey by Ted Miller on 8-15-1975, Recorded L. 2, P. 108. FOUND 1½"PIPE(WIT. S32°W 40.71 Survey by R.S. Scott Assoc., on 4-28-1978, Recorded L. 3, P. 3. 10"CFDAR-33°W 2.3219"BALS FOUND 1½"PIPE & ½"BAR & CAP(WIT.SOUTH 12"BALSAM 2.11-532°W 10"CFDAR 40.71- SOUTH POWER POLE 25.31')				
B. Desc	ription of corner e	evidence found and/or method ap	plied in restoring or reestab	dishing corner:
(H-13)	Found 1½" p S 3* W Bals S 32* W Cer	of Section 34, T 30 N, ipe with ½" rod & cap #1 sam stump 2.32' dar stump 40.7' of original corner.	2018. SURVEY &	ATION PEER GROUP
		ţ	COMMISSIC	on LAB
C. Desc (H-13)	S. ½ corner Set concrete N 20* W 8" N 60* E 9"	Scotch Pine 77.0'	E. tion cap. <b>#18660</b>	ating the position of the corner DF MICHIGATION MARLATT SURVEYOR NO. 18660  available evidence of the corner of th
Signed by	Jonacel	E Marlatt	Date	-7-1995
Surveyor's Michigan License No. 18660 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971				