SURVEY & REMONUMENTATION

Montmorency County Remonumentation

APR 2 4 1995

LAND CORNER RECORDATION CERTIFICATE 1.1 Filing Requirement of Act 74, Mich. P.A. 1970

ber	00012	Page	0120
-----	-------	------	------

For corners in
For corners in COMMISSION
Montmorency
(County)

1. Public Land Survey

2. Property Controlling

Property in Sec.

in Section

5. Private Claims

expressed below:

Miscellaneous

Located in: Montmorence Corner Code ## Twp.

T 32N R 3E

(A-11)APPROVED BY

_ R . T R ___ R _ __ T ..___ R _

T _____ R ____

Ť____R __

STATE OF MICHIGAN MONTMORENCY COUNTY Recorded & Filed

11-02-1994 15:47:19

A. PANGAN-MCELROY REGISTER OF DEEDS

Register of Deeds Stamp & File Number

i. Larry G. Beauregardin a field survey on March do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A-11) GLO post set by Hiram Burnham July 4, 1850.

___ . Recorded Plat

Wits: Y. Pine 5" S 30° W 28 links

Y. Pine 5" N 35° W 12 links

-Ken Ostling P.S. #10068 in 1958 set DOC std. corner & filed Forestry Division Land Corner Record.

Witnesses marked: (12" R. Pine N 20° W 207 links) (8" W. Oak N 45° E 139 links) J. Pine S 66° W 61½ links).

Note: Ostling established this corner by proportionate measurement between corners 2 miles North and $\frac{1}{2}$ mile Sout by Forestry Division survey crew while making a survey in this area. Aspen Gov't. B.T.'s all gone. Checks fair stream crossing North and exactly with North edge of open marsh.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" pipe with a 4" brass cap in good condition and witnesses by Ostling. This corner is 142't East of Co. Rd. #628. (DOC standard corner).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner;

Sec. Cor. Comm. to Sec's 25 & 36, T32N, R2E, & Sec's 30 & 31, T32N, R3E.

Ex. Department of Conservations 1" pipe & 4" brass cap, 6" above ground in good condition, 142'± E. of Co. Rd. 628. Accepted as the best available evidence of the re-establishment of the original condition. corner. Approved by the Peer Group on May 13, 1994.

N 10° W 136.62' (R) 136.81' (M) to spike 23" R. Pine 91.74' (R) & (M) N 45° E 15" W. Oak to spike s 70° W 40.59' (R) & (M) 12" J. Pine to spike S 45° E 68.53' (M) 13" R. Oak to spike

Placed blaze, 20 penny spike & P.S. tag #18654 (typ)

Jany Securizard Date _______ Date _____ Surveyor's Michigan License No. 18654

REVISED JAN., 1983