MAR 1 3 2000

NEWAYGO COUNTY

1999 Newaygo County Remonumentation Project GISTER OF DEEDS

SECTION

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT of Act 74 Mich. P.A. 1970

LINDA M. BROWN

	FILING REQUIR	EMENT of Act 74, Mich.	P.A. 1979 FEB 28 PM	1 09
For corners in Newaygo (County)	Located in:	Corner Code#	Linda M. Br	•
1. Public Land Survey	T <u>11N</u> R <u>11W</u> T R T R	<u>H-1</u>	VOL. 2	284
Property Controlling     in Section     Miscellaneous     Property in Sec.	STR STR STR STR		Register of Deeds_Stamp & File	e Number
4. Lot No, Record	ded Plat		ABCDEFG	JKLM
oo nereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior, Burea Law and/or that the corner policonformance with the rules of Decree of a Court of Law; establist recovered, found as expressed be Note: Not more than 4 carecorded on this can North One Quarter Corner, S	orners, all in the same to ertificate. ection 3, Ensley Township, Ne	of 1970, the comer squiations and rules of the United States decree of a Court of 5 above were in Surveyors or by a sq, re-monumented, wn and range, may be awaygo County, Michigan.	5 6 - 18 - 17 - 16 - 15 - 7 8 - 19 - 20 - 21 - 22 - 9 10 - 30 - 29 - 28 - 27 - 11	- 23 - 24 - - 26 - 25 - - 35 - 36 -
G.L.O. Did not set.  Newaygo County Road Commission Sheet 1" Gas Pipe 20" Oak N25°W 78.4' #1		Glen S. Hackbardt R.L.S. #25844 LCRC #751 March 10, 1987 Found 1" Iron 20" Oak N25°W 78.4' #1 Consumers Pole South 31.77' #4		
Twin White Oak (no bearing				OVER 🔖
B. DESCRIPTION OF COR CORNER:	RNER EVIDENCE FOUND	AND/OR METHOD APPI	LIED IN RESTORING OR RE	ESTABLISHING
condition of the recorded	llegible cap in the centerlin witnesses are: #1 gone, # #4 good condition, #5 gone.	2 good condition, #3 fou	ravel road and in fence line g und (8"-6" Twin Stump S50°E	oing South. The 53.12' Spike in
C. DESCRIPTION OF MC	NUMENT FOR CORNER CORNER:	AND ACCESSORIES ES	STABLISHED TO PERPETU	ATE LOCATING
Removed rod and set a 4' section corner and is acce	' Harrison cast iron monum pted as a careful and faithf	ent 18" long marked "Co ul reestablishment of the	ounty Surveyor" as a substanti original corner.	
Consumers Pole South 32 24" Black Oak N28°E 44.7 20" Red Oak S05°W 43.47	0' Set spike with tag #2243: 27' Top centerline of steel '8' Found spike in East side 7' Set spike with tag #22439 0' Found spike with tag #30	fence post adjacent. #4 of tree.		NORMAN L OCHS

Signed by

Norman L. Ochs

South One Quarter Corner, Section 34, T12N R11W, (Harrison monument) East 13.76'

Date \_\_\_\_\_August 17, 1999

Date \_\_\_\_August 17, 1999

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975

Revised Jan., 1983

THE TAND

Approved by Peer Review Group on <u>August 19, 1999</u>
Norman L. Ochs, County Representative.

1190

## SUBVEY & REMONUMENTATION

## MAR 1 3 2000

A. Description (cont.)

SECTION

Stanley J. Kass R.L.S. #34972 LCRC #925 February 5, 1990

Found 1" Iron Pipe

Witnesses or record not found, however other apparent witness points were found and used.

24" Oak N12°W 58.82'

24" Oak N17°E 39.45'

20" Oak S32°W 47.55'

8" Oak S28°E 42.14'

1/2" Iron road West 13.82'

NOTE: These witnesses were to the South One Quarter Corner, Section 34, T12N R11W

Jack E. Pierson R.L.S. #19305

Either found or set this corner half way and on line between the Northwest Corner and the Northeast Corner of Section 3. (It may have been set by Patrick A. Sallsbury R.L.S. #13594 on February 27, 1974)