MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA H. BROWII

SECTION

LAND CORNER RECORDATION CERTIFICATE '98 MAR 6 PM 12 34 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

A

For corners in Newaygo (County)	Located in:	Corner Code#	Hirt	JM. Dhuw
Public Land Survey	T <u>11N</u> R <u>11W</u> T R T R T R	<u>M-13</u>	vol. 2	73
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR	R	egister of Deeds_Stam	o & File Number
4. Lot No, Record 5. Private Claims, Record 6. Private Claims, Record 6. Private Claims, Record 7. Private Claims, Record 8. Private Claims	_ , in a field survey onSeptem irements of P. A. 74, Michigan P above were in conformance with int manual of survey instructions au of Land Management or by a ints mentioned in lines 3, 4 at the Michigan Board of Land lished, re-established, monume telow: corners, all in the same to certificate.	A. 6, 1970, the content of regulations and rules of the United States a decree of a Court of and 5 above were in Surveyors or by a nted, re-monumented,	1	22 - 23 - 24 -
Southeast Quarter Corner, S	Section 36, Ensley Township,	, Newaygo County, Michigan.	13	

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1838 12" Pine S45°W 27 Links (17.82')#1 13" Pine N05°E 26 Links (17.16')#2

Kent County Road Commission Shows distance East 216.6 to North One Quarter Corner, Section 1, T10N R11W, Solon Township.

Newaygo County Road Commission Sheet 1/2" Iron over 13/4" Pipe Telephone Pole N80°E 83.7' #3 Telephone Pole S04°W 21.2' #4

Newaygo Engineering and Survey Company LCRC #697 September 27, 1985 Found 1/2" Pipe in monument box 2 feet North of the centerline of East and West roads and 2 feet East of centerline of road going North. Set a 4" by 20" Harrison County Surveyor monument in monument box.

"X" in Curb N45°E 34.89' #5 "X" in Curb N45°W 35.78' #6 Road Sign N40°W 41.25' #7 Northwest Corner of Garage \$45°E 154.52' #8 Removed 1/2" Pipe, 1/2" Rod and 3/4" Pipe.

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 4" diameter Harrison monument in monument box in the centerline of bituminous road going North and the centerline of East and West road is 2 feet South. The condition of the recorded witnesses are: #1 thru #4 gone, #5 thru #8 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 4" diameter Harrison cast iron monument marked "County Surveyor" in monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.					
"X" in Curb N45°E 34.95' #5 "X" in Curb N45°W 35.72' #6 Road Sign N40°W 41.25' #7 Northwest Corner of Garage at Foundation S45°E 154.65' #8 1/2" Rod and Cap #22439 at back of curb (on seam) N45°E 35.2 4"-4"-4" Triple Box Elder N13°W 112.20' Set spike and tag in Element Set Signed by Norman Logist Signed by Norman Logist Set Spike and Logist Signed by Norman Logist Set Spike and Logist Signed by Norman Logist Set Spike and Logist Set Spike and Logist Set Spike Signed by Norman Logist Set Spike Set Spike Sp	NORMAN L. 0CHS LAND LAND SURVEYOR SURVEYOR				