MAY 28 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

For corners in Newaygo (County)	Located in:	Corner Code #	Ŏ.	l. furda	M. Brown	
<ol> <li>Public Land Survey</li> <li>Property Controlling</li> </ol>	T <u>11N R 12W</u> T R T R T R S T R	E-11	vol. <b>1</b>	PAGE	216	
in Section 3. Miscellaneous	STR STR	-	Register of Deeds S	tama 2 E	ila Numher	
Property in Sec.	STR		Register of Deeds 3	ramp & r	HC HUILIDOI	
do hereby certify that under recovered, found as expressed		, 19 96 A of 1970, the corner egulations and rules of the United States decree of a Court of 15 above were in Surveyors or by a ed, re-monumented,	10		11	
Note: Not more than a recorded on this	4 corners, all in the same to sertificate.	town and range, may b	e 11	2 33		
Northwest Corner, Sect	ion 33, Grant Township, Nev	waygo County, Michigan	** <del> </del>	•		
A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:						

G.L.O. J.H. Mullett 1838 12" Beech S49°E 47 Links (31.02')#1 18" Beech N36°W 20 Links (13.20')#2

William M. Jacques (County Surveyor) August 29, 1905 Book 8 Page 69 Cedar Stake with glass 40" Pine Stump N11°E 661/2 Links (43,89')#3

Newaygo Engineering and Survey Company Found 1/2" iron June 10, 1978 14" Red Oak N30°E 45.86' Spike in East side of tree. #7 Telephone Riser South 30.70' Top centerline #8 10" Red Oak S39°E 89.40' #9

Lyle S. Shepherd R.L.S. #503 Book 70 Page 42 June 5, 1930 Found Gas pipe in line with fence 33' ± out

NCRC Sheet Iron 24" Oak S68°E 127.2' #4 8" Apple S21°W 52.9' #5 Power Pole N02°W 67.3' #6

Duane F. Wood P.S. #24625 LCRC #964 Found Steel rod in road May 25, 1984 Twin Oak N25°W 37.90' #10 20" Oak N25°E 45.85' #7 Twin Oak South 62.25' #11

OVER 🦠

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ½" Rod 2" below bit inside of 1½" Iron pipe and found remnants of wood stake and the centerline of the East and West road is 2.6 feet South and on line with edge of woods going South and the condition of the recorded witnesses are: #1 thru #3 gone, #4 good condition, #5 gone, #6 good condition, #7 gone, #8 thru #10 good condition, #11 gone, #12 good condition.

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed ½" Rod and 1½" Iron pipe and set a 4" diameter Hamson substantial marker for the section corner and is accepted as a carefu	ul and faithf	ui reestablishment of the	original corner.
36" Oak S60°E 128.05' Set spike and tag in Southeasterly side of tre		·	of Michiga
Power Pole N04°E 67.68' Set spike and tag in East side of pole. #6			NORMAN
Telephone Riser South 30.58' #8			L OCHS
18" Red Oak S40°E 89.40' Found spike in Southwest side of tree. #	:9 "40	•	Z LAND
16"-12" Twin Oak N15°W 37,90' Found spike in Easterly side of tree	a, #10	•	SURVEYOR
½" Rod and cap #24625 North 33.00 #12			00420
Signed by Momoin L. Ochs	Date	September 13, 1996	22439
Norman L. Ochs			AFD LAND
Surveyor's Michigan License No. 22439	Form appro	oved by Michigan State Board	of Land Surveyors, 1975 Revised May 14, 1975

Approved by Peer Review Group On September 17, 1996

Norman L. Ochs, County Representative.

Revised Jan., 1983

## A. Description (cont.)

Newaygo Engineering and Survey Company Found Steel Bar August 24, 1987 Twin Oak N25°W 37.90'#10 20" Oak N25°E 45.85'#7 Twin Oak South 62.25'#11

Charles E. Fricke P.S. #21781 Survey Recorded in Liber 355 Page 3742 November 17, 1992 Twin Oak N25°W 37.9' #10 20" Oak N25°E 45.8' #7 Twin Oak South 62.2' #11 Property Iron North 33.00' #12

> . 2 . 6 .