

MAY 28 1997

COMMISSION

## 1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE, 97 FEB 12 PM 4 45

	TIENTO REGUIN			
For corners in Newaygo (County)	Located in:	Corner Code#	Linda	m. Brown
Public Land Survey     Property Controlling in Section	T 11N R 12W T R R T R T R S T R S T R	F-11	<b>VOL. 1</b> P.	AGE 217
3. Miscellaneous	STR		wieter of Doods Star	on & Eila Number
Property in Sec.	S I R	<u></u>	gister of Deeds_Stam	
4. Lot No, Reco	rded Plat	· · · · · · · · · · · · · · · · · · ·	7 G G	D E F G II J K L
points mentioned in lines 1 and therefore as required in the cur Department of the Interior, Bur Law and/or that the corner p conformance with the rules o	, in a field survey on August 13 uirements of P. A. 74, Michigan P. 2 above were in conformance with rent manual of survey instructions eau of Land Management or by a bints mentioned in lines 3, 4 and the Michigan Board of Land blished, re-established, monument below:	regulations and rules of the United States decree of a Court of 1 5 above were in Surveyors or by a	4	7. — 16. — 15. — 14. — — — — — — — — — — — — — — — — — — —
Note: Not more than 4 recorded on this	corners, all in the same certificate.	town and range, may be	11	23334353
North One Quarter Com	er, Section 33, Grant Town	ship, Newaygo County, Mic		
A. DESCRIPTION OF	ORIGINAL MONUMENT A	ND ACCESSORIES AND/O	OR SUBSEQUENT	RESTORATION:
G.L.O. J.H. Mullett 1838 10" Cedar S05°E 28 Links 8" Cedar N37°W 15 Links ( Lyle S. Shepherd R.L.S. #5 Book 70 Page 42 June 5, Iron and 3 Stones	9,90')#2 03	Found ¾" Gas Telephone Pol	Book 70 Page 133	
Duane Wood P.S. #24625 LCRC #964 April 2, 1990 Found Pipe in road Power Pole S05°W 111.5': Power Pole N05°W 125.0': Centerline Road North 2.3'	#4	•		
B. DESCRIPTION OF REESTABLISHING CO		ND AND/OR METHOD AP	PPLIED IN RESTOR	ING OR
centerline of the drive going	f a ¾" inside diameter of iron p   North is 18 feet West and the one, #4 thru #6 good condition	ipe and the centerline of the Ea centerline of trail going South is	ast and West road is 2.0 s 16 feet West and the	3 feet North (#6) and the condition of the recorded
	MONUMENT FOR CORNE TION OF THE CORNER:	ER AND ACCESSORIES E	STABLISHED TO F	PERPETUATE
Removed 2" iron pipe and a marker for the section corn	1⁄4" pipe and set a 4" diameter h er and is accepted as a careful	larrison cast iron monument 20 and faithful reestablishment of	O" long marked "County the original corner.	/ Surveyor" as a substantial
Power Pole S02°W 111.30 Power Pole N29°W 344.75 Corregated Metal Pipe S63	l' Found spike in West side of p l' Found spike in West side of p l' Set spike and tag in Northeas °W 37.60' Set p.k. nail in South	oole. #5 sterly side of pole. n end.		
Signed by /// Norman L. Ochs	us a cors	Date <u>Septem</u>	ıber 13, 1996	· ·
Surveyor's Michigan Licens		Form approved by Mic	higan State Board of Land	Revised May 14, 1975
Approved by Peer Review Ground Norman L. Ochs, County Repr			NORMAN	Revised Jan., 1983