MAR 1 3 2000

NEWAYGO COUNTY 1999 Newaygo County Remonumentation Project^{REGISTER} OF DEEDS

LHIBA M. BROWN

LAND CORNER RECORDATION CERTIFICATE

SECTION	FILING REQUIRE	MENT of Act 74, Mich	. P.A. 19700 FEB 28 PM	1 09
For corners in			0	7
Newaygo (County)	Located in:	Corner Code#	Linda M. L	Irouse
1. Public Land Survey	T <u>11N</u> R <u>12W</u> T R T R	G-13	$^{\circ}$ VOL. ${f 2}$	298
Property Controlling in Section Miscellaneous Property in Sec.	TR STR STR STR		Register of Deeds_Stamp & File	Niumhar
·				
5. Private Claims	ded Plat		A B C D E F G H I 2 - 6 - 5 - 4 - 3 -	J K L M 2 + 1 -
therefore as required in the curre Department of the Interior, Burea Law and/or that the corner point conformance with the rules of Decree of a Court of Law; established recovered, found as expressed by		ulations and rules ne United States cree of a Court of above were in rveyors or by a re-monumented,	4 - 7 - 8 - 9 - 10 - 5 - 6 - 18 - 17 - 16 - 15 - 7 - 8 - 19 - 20 - 21 - 22 - 9	14 + 13 - 13 - 23 - 24 - 1
Note: Not more than 4 c recorded on this co	orners, all in the same tow ertificate.	n and range, may be	10 - 30 + 29 + 28 + 27 + 11 + 22 + 23 + 24	+
Southeast Corner, Section 33	3, Grant Township, Newaygo Co	unty, Michigan.	12 31 + 32 + 33 + 34 +	35 + 36 -
A. DESCRIPTION OF OR	RIGINAL MONUMENT AND A	ACCESSORIES AND/	OR SUBSEQUENT RESTORA	TION:
G.L.O. N. Brookfield 1836 10" Birch N61°E 10 Links (12" Hemlock N44°W 27 Li	(6.60')#1 nks (17,82')#2	Lyle S. Shepherd R. June 5, 1930 Boo Gas Pipe in centerlii Measured 2668 feet	ok 70, Page 42 ne of gravel. t from the Southeast Comer to	the South One
William M. Jacques (Coun Book 8, Pages 33 and 34 Iron Measured 40 Chair Southwest Corner to the S of Section 34, T11N R12M	August 19 and 20, 1913 ns 48 feet (2688') from the outh One Quarter Corner		ection 33, T11N R12W. cad Commission Sheet .6' #3	
Norman L. Ochs R.L.S. #2 February 23, 1983 Drawi Found 5/8" Rod	ing Number 83020B	12" Elm S14°W 21.: Telephone Pole S73		
Telephone Riser S50°W 66 8" Ash S15°E 49.34' #7	3.75′ #6		OVER ५	>
B. DESCRIPTION OF COR CORNER:	NER EVIDENCE FOUND AN	ID/OR METHOD APPI	LIED IN RESTORING OR REE	STABLISHING
Found 4" Harrison cast iro centerline of the East and W #6 good condition, #7 thru	rest bituminous road is 2 feet ±	y Surveyor" in the cent North. The condition of	terline of bituminous road going f the recorded witnesses are: #	g North and the 11 thru #5 gone,
C. DESCRIPTION OF MO THE POSITION OF THE C	NUMENT FOR CORNER AN	ND ACCESSORIES ES	STABLISHED TO PERPETUA	TE LOCATING
Accepted 4" Harrison cast accepted as a careful and	iron monument marked "Confaithful reestablishment of the	unty Surveyor" as a su e original corner.	ibstantial marker for the sectio	n corner and is
Telephone Riser S60°W 66 Power Pole N15°E 183.55' Street Sign N45°E 64.83' to Stop Sign N37°W 64.40' to	Found spike in West side of centerline of pole.	pole.	STILL OF M NORM * L. OO	HS 🛬

Form approved by Michigan State Board of

Approved by Peer Review Group on <u>August 19, 1999</u>

Norman L. Ochs, County Representative.

Norman L. Ochs

22439

Surveyor's Michigan License No.

A. Description (cont.)

Norman L. Ochs R.L.S. #22439 LCRC #681 September 11, 1985 Found 5/8" Rod. Removed and set a 4" X 20" Harrison cast iron monument marked "County Surveyor". 4" - 10" Twin Ash S15°E 49.28' #7 8" Clump of Elms N15°E 156.55' #8 Street Sign N45°E 48.9' #9 Stop Sign N45°W 43.42' #10

SUBVEY & REMONUMENTATION

MAR 1 3 2000

SECTION