MAR 1 3 2000

1999 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970 '00 FEB 28 PM 1 10

For corners in Newaygo	Located in:	Corner Code #	<i>d</i> :	n. Brown
(County)			(Sinds)	11. Drown
Public Land Survey	T <u>11N</u> R <u>14W</u> T R T R	<u> -1</u>	$^{'}$ vol. $oldsymbol{2}$	306
Property Controlling in Section Miscellaneous	STR STR STR			
Property in Sec.	STR		Register of Deeds Stamp &	File Number
points mentioned in lines 1 and 2 an	, in a field survey on August 9 rements of P. A. 74, Michigan P. A above were in conformance with real transparent or by a conformation of Land Management or by a conformation of Land Stand Michigan Board of Land Stand, re-established, monumented low:	a. of 1970, the corner egulations and rules of the United States decree of a Court of 5 above were in Surveyors or by a ed, re-monumented,	5 6 - 18 - 17 - 16 - 15 7 8 - 19 - 20 - 21 - 22 9	23 - 24 -
Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.		11 + + + +	-} }-	
Northeast Corner, Section 3, Bridgeton Township, Newaygo County, Mic		-	$\begin{array}{c} 12 - 31 + 32 + 33 + 34 \\ 13 \end{array}$	
A. DESCRIPTION OF ORI	GINAL MONUMENT AND	ACCESSORIES AND/	OR SUBSEQUENT RESTO	RATION:
G.L.O. N. Brookfield 1837		William M. Jacques		

eech S17°E 13 Links (8.58')#1 8" Hemlock S62°W 20 Links (13.2') #2 Southeast Corner, Section 34, T12N R14W, East 33'

Book B, Page's 2 and 3 November 15, 1904 Iron Stake

Phillip A. Harrison (County Surveyor) 1881 ± Book A, Pages 29 and 30 12" Hemlock N55°E 72 Links (47.52')#3 12" Hemlock \$111/2°W 391/2 Links (26.07')#4

Lyle S. Shepherd R.L.S. #503 April 21, 1914 Book 26, Page's 10 and 11 Found two old stakes 50 Links (33') apart for Corner to Bridgeton Township and Sheridan Township.

William Fries, Jr. #30389 LCRC #1136 August 21, 1991 Set ½" Iron and cap 1 foot ± North of occupied centerline and on West edge of drive to the South and 33.00' West of fence to North. Held fence to the North to be on Section line common with Section 34 and 35, T12N R14W. Top Fence Post N40°E 45.33' #5 12" Elm S45°E 46.42' #6 Top Fence Post S25°E 44.47' #7 6" Black Cherry N50°W 36.29' #8

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING

Found Wood stake in the centerline of the East and West dirt road. There is no apparent occupation North or South. The condition of the recorded witnesses are: #1 thru #4 gone, #5 thru #8 incorrect position. NOTE: William Fries Jr. #33089 set his 1/2" Rod and cap in the incorrect position.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Wood stake and act a 4" diameter 11ntial

marker for the section corner and is accepted as a care	t iron monument 20" long marked "County Surveyor" as a substan iful and faithful reestablishment of the original corner.
14" Red Pine S17°E 61.42' Set spike with tag #22439 in	East side of the
Fence Post N49°E 49.67' Found spike with tag #30389	Tan ander
10" Cherry N43°W 31.90' Found spike with tag #22439	Top center,
12" Red Pine \$35% / 41 32' Found anily with the year	In Northeasterly side of tree.
12" Red Pine S35°W 41.33' Found spike with tag #2248	in Northerly side of tree.
Southeast Corner of Section 34, T12N R14W, (4" diame	eter Harrison cast iron monument 20" long) East 33 00'
Signed by 1/2 man Locks	Date August 16, 1999
Norman L. Ochs	
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Lahvi Surveyors, Jan 28, 1971
Approved by Peer Review Group on October 28, 1999	evised May 14, 1975
Norman L. Ochs, County Representative.	NORMAN Revised Jan., 1983
11 80	L. OCHS
11. A. G.	
	I LAND