

MAR 02 1999

1998 Newaygo County Remonumentation

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'99 FEB 17 PM 3 33

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo (County)	Located in:	Corner Code#	Linds	VN. Brown
1. Public Land Survey	T <u>11N</u> R <u>14W</u> T R T R T R	K-4	YOL. $oldsymbol{2}$	159
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds_Stamp &	
4. Lot No, Recor 5. Private Claims	ded Plat		A B C D E F G 1 1 1 1 2 6 5 4	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curred Department of the Interior, Burred Law and/or that the corner poconformance with the rules of	_, in a field survey on	nayu, the corner lations and rules le United States ree of a Court of above were in veyors or by a	3 4 -7 -8 -9 -5 6 -18 -17 -16 -7 8 -19 - 20 - 21 -9	
Note: Not more than 4 or recorded on this c	corners, all in the same town ertificate.		$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	┽╂╂╂
East One Quarter Corner, Sc	ection 11, Bridgeton Township, N	ewaygo County, Michiga	n. ₁₃	

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Mullett 1837 10" Hemlock N321/2°W 19 Links (12.54')#1 18" Beech S58°W 13 Links (8.58')#2

County Surveyor's Witness Book 24" Pine Stump S56°E 19 Links (12.54')#3 24" Pine Stump N38°E 30 Links (19.8')#4

Southwest Corner House N45°E 123.97' #10 Westerly Leg Electric Tower S21°E 238.61' #13

Ralph A. Smith R.L.S. #3421 June 16, 1950 Axle Shaft

Lyle S. Shepherd R.L.S. #503 Book 70 Page 69 1930 3/4" Pipe 9" Elm N74°E 87.6' #5 10" Twin Elm N41°50'E 103.0' #6 12" White Pine N05°05'E 218.0' #7

Lyle S. Shepherd R.L.S. #503 Book 70 Page 69 1931 3/3" Gas Pipe 18" Twin Cherry N30°±E 112.4' #8 14" Elm N65°±E 87.2' #5

OVER &

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1/2" Rerod in 1" X 9" Iron pipe slipped over a 1" X 12" Iron rod driven into a 1" X 10" Iron pipe that broke off. The centerline of North and South blacktop road is 37 feet West and the centerline of gravel road going East is 6 feet North and centerline of gravel road going West is 5 feet South and the condition of the recorded witnesses are: #1 thru #9 gone, #10 good condition, #11 and #12 gone, #13 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 1/2" Rerod, 1" X 9" Iron pipe that was over a 1" X 12" Iron rod and set a 23/4" diameter Harrison cast iron monument 20" long marked "County Survey" over 1" X 10" Iron pipe in monument box as a substantial marker for the quarter corner and is accepted as a careful and faithful reestablishment of the original corner. OF MICHIGAN

Railroad Tie Fence Post S05°W 31.98° P.K. in Southwest side of		L. OCHS
6" Red Pine S66°W 110.00' Found spike in Southeast side of	u ee.	多水車 LAND_ 車
12"-12"-14" Triple Elm N28°E 57.20; Found spike in West sid	e of tree.	SURVEYOR ,
Signed by Morman L. Ochs	Date November 5, 1998	22439
Norman L. Ochs		RED LAND S
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board	of Land Surveying Jan 28 355 T Revised May 14, 1975
Approved by Rear Peyfow Group on December 22, 1998		Revised Jan., 1983

Norman L. Ochs, County Representative.

A. Description (cont.)

Newaygo County Road Commission Sheet %" Pipe
14" Elm N65°E 87.2' #5
29" Twin Elm N42°E 112.2' #6
18" Twin Cherry N30°E 112.4' #8
Power Pole Southwest 82.2' #9

Patrick A. Salisbury R.L.S. #13594 September 16, 1974 Found Axle Shaft Power Pole S72°W 85.73' #9 Southwest Corner House N39°E 123.97' #10 Power Pole S79°E 112.12' #11

William B. Batzer, Jr. R.L.S. #13026 1979 Found 3/" Iron pipe Street Sign N17°E 39.42' #12 Westerly Leg Electric Tower S21°E 238.76' #13

SURVEY & REMONUMENTATION

MAR 02 1999

SECTION