REGISTER OF DEEDS

YTHUGO COUNTY

COMMISSION

1993 NEWAYGO COUNTY REMONUMENTATION PRODECTION TO GGOOD

LAND CORNER RECORDATION CERTIFICATE

Carlo Best of Comment of Comment	Filing Requi	rement of Act 74, Mich. P.A. 19	∻0 4 JRN 21 PM 3 25
For corners in Newaygo	Located In:		Marlene Toogood
1. Public Land Survey	T _12N R _12W T R T R T R	_A-2	VOL 001 PAGE 14
in Section S 3. Miscellaneous S	T R	F	Register of Deeds Stamp & File Number
4. Lot No, Recorded 5. Private Claims			A B C D E F G H I J K L
I, Norman I. Ochs in a field of hereby certify that under requirement in lines 1 and 2 above were in conform current manual of survey instructions of Management or by a decree of a Court of above were in conformance with the rule Court of Law; established, re-established expressed below:	s of P.A. 74, Michigan P.A. lance with regulations a the United States Depa Law and/or that the corr s of the Michigan Board	A. of 1970, the corner points mentioned and rules therefore as required in the artment of the Interior, Bureau of Land per points mentioned in lines 3, 4 and 5 of Land Surveyors or by a Decree of a	4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			11
on this certificate. W14 Corner, Section 6, B A. Description of original monume		nd/or subsequent restoration:	12 31 32 33 34 35 36
G.L.O. (16.5 8" Ironwood S 68°W 25 LK 8" W. Ash N38°W 20 LKS # (13.2') 1949 Lyle Shepherd RLS Used W ¹ 4 Post Sec. 6 for West Emerald Plat.	') Newaygo S#1 7-8-85 2 FD 3/4" P.Pole NW corn #503 NW corn T. Pole	Eng. & Survey Co.	1 7

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

In 1949 Lyle S. Shepherd created the "WEST EMERALD" Plat. Located in the W_2 of section 6. He found the W1/4 corner. Shepherd set a conc. mon. S89046'00" E 300.80 ft for the NW corner of said plat. and he measured S89046'00" E 867.60 ft to the W 1/8th corner on the E & W $\frac{1}{4}$ line. In 1985 I, Norman L. Ochs found a 3/4" pipe, as I also did in 1993. I replaced it with a 4" Harrison Cast Iron Monument. I measured 867.82 feet from W-1/4 corner to the W-1/8th corner on the East & West 1/4 line in 1993.

Condition of recorded witnesses is; #1 Gone, #2 Gone, #3 Good condition, #4 Good condition, #5 Good condition, #6 Good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted 4" Harrison Cast Iron Monument as a substantial marker for the $\frac{1}{4}$ corner and is accepted as a careful and faithful re-establishment of the original corner.

P. Polc S14°E 41.56' Spike in Sw side of pole #3 T. Pole N26°E 49.49' Spike in West side of pole #6

(cabins are the first 2 south of main bldg.) Top & Well N370W 79.50'

NE corner cabin N58°W 29.22' #4

NE corner cabin \$33°W 40.85' #5

Signed by Norman L. Ochs

Date December 28, 1993

Surveyor's Michigan License No. 22439
Approved by Peer Review Group on 22439 December 29, 1993 Norman L. Ochs, County Representative

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED JAN., 1983

OF BICHICA

NORMAN

L. OCHS LAND Surveyor

22439 SED LAND