

MAR 0 2 1999

NEWAYGO COUNTY REGISTER OF DEEDS 1998 Newaygo County Remonumentation Project LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATES FEB 17 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

SECTION				
For corners in Newaygo (County)	Located in:	Corner Code#	Linda M.	Brown
1. Public Land Survey	T <u>12N</u> R <u>13W</u> T R T R	<u>E-7</u>	YOL. 2	194
Property Controlling     in Section     Miscellaneous     Property in Sec.	STR STR STR STR		Register of Deeds Stamp	& File Number
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior, Burea Law and/or that the corner poir conformance with the rules of Decree of a Court of Law, establic recovered, found as expressed be	, in a field survey on June 15 rements of P. A. 74, Michigan P.A. above were in conformance with reg nt manual of survey instructions of u of Land Management or by a de nts mentioned in lines 3, 4 and 6 the Michigan Board of Land S shed, re-established, monumented blow: orners, all in the same tow	of 1970, the corner gulations and rules the United States ecree of a Court of 5 above were in surveyors or by a d, re-monumented,	5 6 18 17 16 7 8 19 20 21 9	- 3 - 2 - 1 - 1 - 10 - 11 - 12 - 15 - 14 - 13 - 14 - 13 - 14 - 12 - 22 - 23 - 24 - 14 - 15 - 15
	6, Garfield Township, Newaygo	County, Michigan.	$\frac{12}{13}$ $\frac{31}{3}$ $\frac{32}{33}$ $\frac{33}{13}$	34 + 35 + 36 -

# A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. J.H. Mullett 1837 10" Beech N70°W 38 Links (25.08')#1 6" Beech S15°E 40 Links (26.4')#2

Newaygo County Road Commission Sheet Monument Box

Patrick A. Salisbury R.L.S. #13594 Consumers Power Company Section Break, Section 20, T12N R13W, 1968 Found monument box.

Winfield S. Merrill (County Surveyor) Book A Pages 87 and 88 April 13, 1887 Book A Pages 113 and 114 March 27 to April 3, 1889 36" Pine \$591/2°E 80 Links (52.8')#3 6" Red Oak N60°E 67 Links (44.22')#4

Ralph A. Smith R.L.S. #3421 Book 56 Pages 50 and 55 June 9, 1952 Monument box

OVER &

Revised Jan., 1983

### B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 12" bolt with 3" X 3" head in monument box on line ± with the centerline of the North and South bituminous road and the centerline of the East and West bituminous road is 2.5 feet ± South. The condition of the recorded witnesses are: #1 thru #4 gone, #5 and #6 good condition, #7 and #8 gone.

# C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Bolt and monument box and set a 23/2" X 20" Harrison cast iron monument marked "County Survey" in new 8" diameter monument box as a substantial marker for the section comer and is accepted as a careful and faithful reestablishment of the original corner.

Power Pole S40°W 65.25' Found P.K. nail with tag (illegible) in Southeasterly side of pole. #5 Power Pole N40°W 61.61' Found P.K. nail with tag (illegible) in Northeasterly side of pole. #6 12" Red Oak (blazed) N43°E 61.32' Found spike in Northwest side of tree. 34" Maple S70°E 108.33' Set spike with tag #22439 in North side of tree.

Signed by_	Moman	L. Och	<u> </u>	PateOctober 20, 1998
_ ,_	Norman L. Ochs			
Surveyor's Michigan License No. 22439		Form	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975	

Approved by Peer Review Group on October 22, 1998 Norman L. Ochs, County Representative.



# A. Description (cont.)

Maurice J. Rosema R.L.S. #27459
March 1987 Found 1" square bar in monument box.
Power Pole Southwest 65.32' #5
Power Pole Northwest 61.64' #6
50" Oak Northeast 78.56' #7
Concrete curb Southeast 45.39' #8

SURVEY & PENONUMENTATION

MAR 0 2 1999

SECTION