MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE '98 MMR 6 PM 12 35 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo (County)	Located in:	Corner Code#	Finder)	n. Brown
1. Public Land Survey	T <u>12N</u> R <u>13W</u> T R T R	-3	VOL. $oldsymbol{2}$	79
Property Controlling in Section Miscellaneous	STR STR_ STR			
Property in Sec.	STR		Register of Deeds Stamp &	File Number
do hereby certify that under requoints mentioned in lines 1 and 2 therefore as required in the curr Department of the Interior, Bure Law and/or that the corner possible conformance with the rules of Decree of a Court of Law; establic recovered, found as expressed to Note: Not more than 4 or recorded on this of	, in a field survey on February ulrements of P. A. 74, Michigan P.A. 2 above were in conformance with recent manual of survey instructions of au of Land Management or by a coints mentioned in lines 3, 4 and the Michigan Board of Land blished, re-established, monuments below: corners, all in the same to certificate.	of 1970, the corner agulations and rules of the United States decree of a Court of 5 above were in Surveyors or by a sed, re-monumented, we and range, may be	5	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
Southeast Corner, Sectio	n 3, Garfield Township, Nev	vaygo County, Michigar	13 14 14 14 14 14 14 14	

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. J.H. Mullett 1839 12" Maple N65°E 33 Links (21.78')#1 24" Pine S86°W 26 Links (17.16')#2

Winfield S. Merrill (County Surveyor) Book A Pages 65 and 66 May 13, 1882 Stone Corner Crockery buried 36" Pine S801/2" E 421/2 Links (28.05')#3 40" Pine N78°W 81 Links (53.46')#4

Newaygo County Road Commission Sheet ron Power Pole N63°W 76.2' #9 20" Eim S36°W 62.05' #7 Telephone Pole S86°E 21.75' #5

Lyle S. Shepherd R.L.S. #503 Witness Book Number 2 Page 81 Telephone Pole East 20.7' #5 18" Elm S20°W 101.6' #6 12" Elm S33°W 61,2' #7

Lyle S. Shepherd R.L.S. #503 Book 82 Page 10 November 8, 1948 1/2" Solid rod Telephone Pole N601/2°E 25.0′ #8 20" Elm S34°W 62.3' #7 18" Eim S191/2°W 101.8' #6

OVER &

Revise.

Iron

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

13

Found Railroad spike over 11/4" pipe over a 1/2" solid iron and old wood stake. The centerline of the North and South road is 4.5 feet West and the centerline of the road going West is 9 feet North and the centerline of a drive going East is 15 feet North. The condition of the recorded witnesses are: #1 thru #8 gone, #9 thru 11 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Railroad spike, 11/2" pipe, 1/2" solid iron and old wood stake and set a 4" diameter Harrison cast iron monument

20" long marked "County Surveyor" as a substantial marker reestablishment of the original corner.	er for the sec	ction corner and is accep	ted as a careful and faithfu
Power Pole N60°W 76.22' Found spike in Southwest side			
Telephone Pole S46°W 110.36' Found Consumer Power (Company tag	g in West side of pole. #1	ı 0
Telephone Riser S38°E 32.53' Top center. #11			200 186 186 A SA
12" Elm S23°E 62.41' Set spike with tag in West side of tre	e.		OF BICK MI
8" Elm N12°W 106.78' Set spike with tag in Northeast side			The second second
			NORMAN NORMAN
Signed by Morman L. Ocho	Date	September 8, 1997	L. OCHS *
Norman L. Ochs			* LAND ⊁
Surveyor's Michigan License No. 22439	Form appr	oved by Michigan State Board o	of Land Surveyors, Jan 28, 1971
			% C Revised Way 14, 1975
Approved by Peer Review Group on September 9, 1997			Revised Jan 1983
Norman L. Ochs, County Representative.			A Francisco SU
NYO			MANAGEMENT OF THE PARTY OF THE

A. Description (continued)

C.F. Zimmerman P.E. #7301 Book Garfield Township Iron 1949 Telephone Pole East 21.75' #5 18" Elm S20°W 101.9' #6 12" Elm S33°W 62.4' #7 Telephone Pole N60°E 25.0' #8

Patrick A. Salisbury R.L.S. #13594 1973 1½" Pipe Telephone Pole S85°E 21.61' #5 Power Pole N62°W 75.80' #9 Consumer Power Company tag on West side of Telephone and Power Pole S45°W 110.22' #10

Newaygo Engineering and Survey Company
October 6, 1983 Found 1¼" Pipe and raised with railroad spike. Drawing Number 83180AC
Telephone Pole S85°E 21.61' #5
Power Pole N62°W 75.80' #9
Telephone Riser top center S40°E 32.47' #11

Newaygo Engineering and Survey Company
May 21, 1987 Railroad spike Drawing Number 87106M&B
Power Pole N62°W 75.80' #9
Consumer Power Company tag on West side of Telephone and Power Pole 110.25' #10

į. į.