

MAR 02 1999

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE SECTION FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PM 3

For corners in Newaygo (County)	Located in:	Corner Code #	Lind	a M. Bro
1. Public Land Survey	T <u>12N</u> R <u>14W</u> TR TR	<u>C-1</u>	VOL. 2	165
 Property Controlling in Section Miscellaneous Property in Sec. 	TR STR STR STR		Register of Deeds Stamp &	
4. Lot No, Reco	orded Plat		1 A B D E F G H	
points mentioned in lines 1 and therefore as required in the cur Department of the Interior, Bure Law and/or that the corner per conformance with the rules of Decree of a Court of Law; estat recovered, found as expressed in		A. of 1970, the corner regulations and rules of the United States decree of a Court of 15 above were in Surveyors or by a ed, re-monumented,	5 6 - 18 - 17 - 16 - 15 7 8 - 19 - 20 - 21 - 22 9	23 - 24 -
recorded on this	corners, all in the same to ertificate.	wn and range, may be	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Northwest Corner, Section 5	i, Sheridan Township, Newayg	o County, Michigan.	12 31 + 32 + 33 + 34	35 + 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1837 18" Lynn S25°E 29 Links (19,14')#1. 10" Beech \$87°W 17 Links (11.22')#2 Southeast Corner, Section 31, T13N R14W, West 43 Links (28.38')#3

Newaygo County Road Commission Sheet Bolt in pavement West Head wall \$42°W 49.3' #4 "X" on Station Drive N12°E 46.9' #5 "X" on Oil Drain Floor N45°E 60.0' #6

Raiph A. Smith R.L.S. #3421 June 24, 1965 Book 80 Page 80 Bolt 2.68 feet North of centerline of pavement.

John C. Brewster (County Surveyor) Book A Page 125 April 2, 1891 Old Stake, Stone 20 inches long and two glass bottles.

Lyle S. Shepherd R.L.S. #503 Book 84 Page 29 1950 Bolt in pavement Culvert Head wall S42°W 49.3' #4 Culvert Head wall South 36.3' #7 Dayton Township Corner is 28.4' West #3

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1/2" X 17" Copper Rod in monument box. The centerline of the East and West bituminous road is 1 foot South and the centerline of the bituminous road going South is 18 feet ± West. The condition of the recorded witnesses are: #1 and #2 gone, #3 good condition, #4 gone, #5 old concrete drive broken up, unable to find "X", #6 bearing and distance lands in concrete, could not locate "X", #7 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

new 8" diameter monument box as a substantial marker for reestablishment of the original corner.	20" Harrison cast iron monument market the section corner and is accepted as a c	d "County Survey" in careful and faithful
Southwest Corner, Section 32, T13N R14W (23/2" X 20" Harr 34" Maple S15°E 59.46' Set spike with tag #22439 in Norther	SEIBIN SIGA OF TRAC	ox) West 28.50' #3
vvest end of Corrugated Metal Pipe S48°W 51 10' Set P K w	with tan #22430	The same of the sa
22" Walnut N05°E 72.82' Set spike with tag #22439 in West	side of tree.	SECTION WICHIGH
Power Pole S49°E 69.67' Set spike and tag #22439 in North	side of pole	
Signed by Norman L. Ochs	Date October 15, 1998	NORMAN L. OCHS
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land	L CHOVEYOR
Approved by Peer Review Group on October 22, 1998		Deviced May 24 3 975
Norman L. Ochs, County Representative.		Mediacilamines 31/2
1 n 1		784. 74 1 N D 1 25