

MAY 28 1997

1996 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

COMMISSION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

For corners in Newaygo (County)	Located in:	Corner Code #		Line	las M.	Bisi
Public Land Survey Property Controlling in Section Miscellaneous	T 12N R 14W T R T R T R S T R S T R		VOL. 1	PAGE	231	
Property in Sec.	S T R	Rea	ister of Deeds S	tamp & Fil	le Numbéi	
do hereby certify that under recoints mentioned in lines 1 and therefore as required in the cur Department of the Interior, Bur Law and/or that the corner pronformance with the rules of Decree of a Court of Law; esta recovered, found as expressed Note: Not more than 4 recorded on this	, in a field survey on October 4 quirements of P. A. 74, Michigan P.A. 2 above were in conformance with re- rent manual of survey instructions of eau of Land Management or by a d oints mentioned in lines 3, 4 and of the Michigan Board of Land S blished, re-established, monumented below. I corners, all in the same to a certificate.	of 1970, the corner gulations and rules the United States ecree of a Court of 5 above were in surveyors or by a d, re-monumented,	7 C D 2	E F G	11	L M
Northwest Corner, Secti	on 17, Sheridan Township, N	lewaygo County, Michigan	13	·	_lll	لــــــــــــــــــــــــــــــــــــــ

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John H. Mullett 1838 10"Hemlock S32°W 11 Links (7.26')#1 10" Lynn N45°W 27 Links (17.82')#2

Lyle S. Shepherd's Witness Book Number 2 Page 66 Found Pipe Nothing near for witnesses. Cedar Stake and gaspipe in stone pile

Patrick A. Salisbury R.L.S. #13594 January 2, 1973 Found 1" Pipe and rocks 1' below grade raised with 1/2" Rod and 1/4" Pipe over rod 8" Cherry S05°±W 64.40' #3 36" Maple S46°±W 224.72' #4 8"-8" Twin Apple N10°±W 61,69' #5

NCRC Sheet Pipe in stone

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found threaded bolt, raised with 1½" Well Point, raised with ¾" pipe and 5/8" rod inside with pointed stone next to it and the centerline of road going East is 7 feet South and the centerline of road going South is 8 feet East and the centerline of gravel drive going North is 2 feet West and the old fence line going North is 7 feet West and the East and West fence line on ground is 12 feet South and the condition of the recorded witnesses are: #1 and #2 gone, #3 thru #5 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER: .

Removed threaded bolt, 1½" Well Point, ¾" pipe, 5/8" rod and pointed stone and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

16" Cherry S10°W 64.02' Set spike with tag in West side of tree, #3				
40" Maple S46°W 224.72' Spike in Northwest side of tree, #4	•			
16"-16" Twin Apple North 61.86' Set spike with tag in East side of tr	ee. #5		•	
22" Elm S37°W 27,66' Nail in root in Northwest side of tree.			•	
Signed by Homan L. Ochs	Date	October 17.	. 1996	
Norman L. Ochs				_
Surveyor's Michigan License No. 22439	Form appro	ved by Michigan	n State Board of Land Surveyors, Jan 28, 1971	
			Revised May 14, 1975	
Approved by Peer Review Group On October 24, 1996			Revised Jan., 1983	

Norman L. Ochs, County Representative.

