MAR 02 1999

### 1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'99 FEB 17 PM 3 33

## SECTION

### LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo	Located in:	Corner Code#	<i>D</i>	
(County)			Sinda M	. Diam
Public Land Survey	T <u>12N</u> R <u>14W</u> T R T R	E-1	, Vol. <b>2</b>	
Property Controlling     in Section     Miscellaneous	TR STR ST R ST R		YUL, 🚑	16
Property in Sec.	STR		Register of Deeds Stamp & File N	lumber
no hereby certify that under red points mentioned in lines 1 and therefore as required in the curn Department of the Interior, Bure Law and/or that the corner po conformance with the rules of Decree of a Court of Law; estal recovered, found as expressed to	, in a field survey onMay 13 uirements of P. A. 74, Michigan P.A. 2 above were in conformance with re- rent manual of survey instructions of reau of Land Management or by a d rent mentioned in lines 3, 4 and the Michigan Board of Land S lished, re-established, monumented	of 1970, the corner gulations and rules the United States ecree of a Court of 5 above were in surveyors or by a d, re-monumented,	A B C D F G H I J  2 - 6 - 5 - 4 - 3 - 2  3 - 4 - 7 - 8 - 9 - 10 - 11  5 - 18 - 17 - 16 - 15 - 14  7 - 19 - 20 - 21 - 22 - 23  9 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	3 - 24 -
Note: Not more than 4 or recorded on this o	corners, all in the same tow ertificate.	vn and range, may be	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	25

# A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1837 24" Beech S54°E 50 Links (33') #1 6" Beech S25°W 7 Links (4.62') #2 Southeast Corner, Section 32, T13N R14W, West 30 Links (19.80')#3

Northwest Corner, Section 4, Sheridan Township, Newaygo County, Michigan.

Newaygo County Road Commission Sheet **Axle Shaft** Telephone Pole N15°E 52.4' #4 Telephone Pole \$40°E 55.3' #5 Power Pole S60°W 72.7' #6

Lyle S. Shepherd R.L.S. #503 January 17, 1947 Book 81C Page 16 Monument Box in pavement

Ralph A. Smith R.L.S. 33421 Book 84 Pages 80 and 81 June 24, 1965 Monument Box Southeast Corner, Section 32, T13N R14W. West 30 Links (19.80')#3

### B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1½"  $\times$  (1"  $\times$  1" top) 38" Axle Shaft in monument box. The centerline of the East and West bituminous road is 4 feet  $\pm$ North and the centerline of the bituminous road going South is 2 feet ± East. The condition of the recorded witnesses are: #1 and #2 gone, # 3 good condition, #4 thru #6 gone.

### C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Axle Shaft and monument box and set a 23/2" X 20" Harrison cast iron monument marked "County Survey" in a new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful

reestablishment of the original corner.	i and a second section (condition)
Power Pole S54°W 67.42' Found spike with tag #22439 in No Found P.K. nail in seam of concrete curb S15°E 53.65'	
6" Cherry N50°W 92.00' Found spike in Easterly side of tree.	
lelephone Pole N36°E 59.20' Set spike with tea #22/30 in M	font side of male
Southwest Corner, Section 33, T13N R14W (23/2" X 20" Harri	son cast iron monument in monument box) West 19.93'
Signed by // Binan K. Clas Norman L. Ochs	DateOctober 15, 1998
Cum revende & Colores & Colores	Form approved by Michigan Managerd of Land Surveyors, Jan 28, 1971  Revised May 14, 1975
Approved by Peer Review Group on October 22, 1998	OF MICH, III. Revised May 14, 1975
Norman L. Ochs, County Representative.	OF MICH GLIVEYOLS, Jail 28, 1971 Revised May 14, 1975 Revised Jan., 1983

Revised Jan., 1983 NORMAN

L: OCHS LAND SURVEYOR N. 22439 PED LAND