

MAR 02 1999

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

\_

'99 FEB 17 PM 3 3

SECTION FILING R

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo (County)	Located in:	Corner Code#	Lin	ea M. Brown
1. Public Land Survey	T_12N R 14W T R T R	F-1	YOL. <b>2</b>	168
Property Controlling in Section     Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds_Stamp & I	
points mentioned in lines 1 and 2 therefore as required in the curr Department of the Interior, Bure Law and/or that the corner po conformance with the rules of Decree of a Court of Law; estab recovered, found as expressed by	irements of P. A. 74, Michigan P.A. of 1976 above were in conformance with regulation on the manual of survey instructions of the Uranu of Land Management or by a decree of ints mentioned in lines 3, 4 and 5 above the Michigan Board of Land Surveyor lished, re-established, monumented, re-melow:	O, the corner us and rules uited States f a Court of were in rs or by a onumented,	5	- 2 - 1 - - 11 - 12 - - 14 - 13 - - 23 - 24 -
North One Quarter Corner, S	ection 4, Sheridan Township, Newayg	go County, Michigan.	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	+ 35 + 36 -

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Not set.

Newaygo County Road Commission Sheet 1" Iron Monument Box 8" Locust N40°W 43.6' #1 30" Elm South 27.6' #2

Patrick A. Salisbury R.L.S. #13594 8"
Plat of "Fremont Farms". The Point of Beginning and the Northwest Corner of said plat is 626.71 feet East of the North One Quarter Corner of Section 4.

April 3, 1975 Recorded in Liber 10 of plats, Pages 6 thru 8

Lyle S. Shepherd R.L.S. #503 Book 81C Page 16 January 17, 1947 Iron in Monument Box in pavement.

Patrick A. Salisbury R.L.S. #13594
December 18, 1972 Drawing Number 72165P
1" Iron in monument box
8" Locust N40°W 43.6' #1
30" Elm South 27.6' #2

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1½" X 35" Shaft in monument box on line ± with a brush and tree row going South and the centerline of the East and West bituminous road is 2 feet North. The condition of the recorded witnesses are: #1 and #2 gone.

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Shaft and monument box and set a 2%" X 20" Harrison cast iron monument marked "County Survey" in new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

reestablishment of the original comer.	
1⁄2" Rerod with cap #30389 N18°W 52.40′	
Power Pole N37°W 63.40' Found P.K. nail with tag #22439 in	Easterly side of note
1/2" Rerod South 50.00'	Lasterry side of pole.
Power Pole S10°W 44.40' Found P.K. nail with tag "Advanced	d C
South One Quarter Corner Section 23 Table Date (227)	a Survey & Map" in West side of pole.
South One Quarter Corner, Section 33, T13N R14W (23/11 X 2) West 16.65'	20" Harrison cast iron monument in monument box)
West 16.65'	,
Signed by // man a // Chr	Date October 15, 1998
Norman L. Ochs	Date October 15, 1998
Surveyor's Michigan License No. 22439	Form approved by Minking wasses.
	Form approved by Michigan Surveyors, Jan 28, 1971
Approved by Peer Review Group onOctober 22, 1998	Revised May 14, 1975
Norman L. Ochs, County Representative.	Revised Jan., 1983
$M \mathcal{O}_{\mathcal{O}}$	NORMAN
7/. h, O.	★ L- OCHS ★