

MAR 02 1999

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

36

'99 FEB 17 PM 3 33

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo (County)	Located in:	Corner Code #	Linds	M. Brown
1. Public Land Survey	T 12N R 14W T R T R	<u>H-11</u>	vol. 2	172
Property Controlling in Section Miscellaneous	STR STR			
Property in Sec.	s rR	***************************************	Register of Deeds Stamp & Fi	ile Number
4. Lot No, Reco	orded Plat		A B C D E F G H	
points mentioned in lines 1 and therefore as required in the cur. Department of the Interior, Bure Law and/or that the corner poponformance with the rules of	, in a field survey on	A. of 1970, the corner egulations and rules of the United States decree of a Court of i S above were in	3 4 7 8 9 10 5 6 18 17 16 15 7 8 19 20 21 22 22	

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

North One Quarter Corner, Section 34, Sheridan Township, Newaygo County, Michigan. 13

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Mullett 1838 10" Hemlock S85°E 22 Links (14.52')#1 10" Maple N34°W 28 Links (18.48')#2

Winfield S. Merrill (County Surveyor) 1894 County Surveyor's Witness Book, Page 154 30" Pine N55°W 27 1/8 Links (17.90')#3 34" Pine S55°E 7½" Links (4.95')#4 Norman L. Ochs R.L.S. #22439

10

11

LCRC#602 December 22, 1963 Found old wood stake ± .20 under ground on the West side of 12" fence post. Fence going North, South and East. Removed old wood stake and Set 1½" Well Point. Reset old wood stake .20 feet East of Well Point. Corner is ± 164 feet South of South top of hill.

16" White Oak N11°W 38.78' #5 8" Maple \$22°E 33.00' #6

30" Pine Stump N50°E 17.62' #3

34" Pine Stump \$52°E 4.87' #4

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found Well Point (11/4" X 32") on line with remnants of fence going North and South. The condition of the recorded witnesses are: #1 thru #3 gone, #4 and #5 stump, #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Well Point and set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

34" Pine Stump S58°E 4.87' to face, #4 18" Oak Stump N10°W 38.8' to centerline, #5	
ody Strill N In M 20.9, to Centerline #2	
14" Maple (blazed) S22°E 32.94' Found spike in West side of tree. #6	
16" White Oak (blazed) N35°W 44.91' Set spike in west side of tree. #6" 10" Red Oak (blazed) N47°E 16.11! Set spike with tag #22439 in West side of tree.	
10" Red Oak (blazed) NA7°E 16 141 Cost spike with tag #22439 in West side of tree.	
12" Red Oak (blazed) S87°E 26.44' Set spike with tag #22439 in Northwest side of tree.	
Signed by Norman J. (Talka) Date December 18, 1998	
Norman L. Ochs	
Surveyor's Michigan License No. 22439	
Torn approved by Michigan State Board of Land Surveyors, Jan 28, 1971	
Approved by Peer Review Group on December 22 4000 Revised May 14 1075	
Norman L. Ochs, County Representative. Revised Jan., 1983	
$M \circ M$	
NORMAN NORMAN	

NORMAN
LI OCHS
LAND
SURVEYOR
NO.
22439