MAR 0 2 1999

SECTION

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970 '99 FEB 17 PM 3 33

For corners in Newaygo (County)	Located in: C	orner Code#	Linds	M. Brow
1. Public Land Survey	T <u>12N</u> R <u>14W</u> T R	<u> -11</u>	VOL. $oldsymbol{2}$	174
Property Controlling in Section Miscellaneous	TR STR STR			
Property in Sec.	STR		egister of Deeds Stamp & File	Number
points mentioned in lines 1 and 2 therefore as required in the curred Department of the Interior, Burea Law and/or that the corner poisonformance with the rules of Decree of a Court of Law; establine recovered, found as expressed by	, in a field survey on	a, the corner a and rules ated States a Court of were in s or by a enumented,	A B C D E F G H I 2 - 6 - 5 - 4 - 3 - 3 4 - 7 - 8 - 9 - 10 - 5 6 - 18 - 17 - 16 - 15 - 7 8 - 19 - 20 - 21 - 22 - 9	+ + -
Note: Not more than 4 c recorded on this c	orners, all in the same town and ertificate.	range, may be	10 30 + 29 + 28 + 27 + 11	26 + 25 -
Northeast Corner, Section 34	, Sheridan Township, Newaygo Count	y, Michigan,	12 31 + 32 + 33 + 34 +	35 + 36 -
A DESCRIPTION OF OF	COBIAL REGRISSION			

. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Mullett 1838 10" Hemlock N52°W 15 Links (9.9')#1 10" Hemlock N85°E 12 Links (7.92')#2

Winfield S. Merrill (County Surveyor) Book A, Page 133 January 19, 1894 40" Pine N28°E 20 Links (13.2')#3

Lyle S. Shepherd R.L.S. #503 Book 26, Page 10 April 21, 1914 Measured 40.50 Chains (2673') from the Northeast Corner to the East One Quarter Corner of Section 34.

William M. Jacques (County Surveyor) Book 18, Page 89 April 22, 1914 Found old stake

Norman L. Ochs R.L.S. #22439 April 18, 1978 LCRC #600 Found 3/2" Pipe ± 4' long (±3' above ground). Also by Pipe and wood fence post found a 3/8" pin \pm 10" under ground 5" - 5" Twin Maple N12°W 8.49' #4 14" Red Oak S68°W 1.75' #5 12" - 12" - 10" Triple Red Oak S75°E 51.03' #6

RED

CHAI

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 3/2" X 40" Pipe and brown glass on line with remnants of fence going East. The corner is at the end of old North and South woven wire fence and the top of bank is 12 feet ± East. The condition of the recorded witnesses are: #1 thru #3 gone, #4 thru #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Pipe and set a 4" diameter Harrison cast iron monument 36" level r.

as a substantial marker for the section corner and is accepted	ment 55° long marked "County Surveyor" on top of brown glass I as a careful and faithful reestablishment of the original corne
10" - 12" Twin Maple (blazed) N12°W 8.55' Found spike in Ea 24" Red Oak (blazed) S65°W 1.80' Found spike in North side 16" - 16" - 14" Triple Red Oak (blazed) S75°E 51.07' Found s 6" Beech (blazed) S26°E 9.93' Set spike with tag #22439 in N	of tree, #5
Signed by Norman L. Ochs	Date <u>December 18, 1998</u>
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group on <u>December 22, 1998</u> Norman L. Ochs, County Representative.	NORMAN Revised May 14, 1975 Revised Jan., 1983 NORMAN L. OCHS