

MAR 0 2 1999

1998 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'99 FEB 17 PM 3 34

Linds M. Drown

25

36

26

35

SECTION For corners in Corner Code # Located in: Newaygo (County) VOL. 2I-13 T 12N R 14W 1. Public Land Survey 2. Property Controlling in Section Miscellaneous Register of Deeds Stamp & File Number Property in Sec. , Recorded Plat 4. Lot No. 5. Private Claims 3 2 1 2 6 5 3 I, Norman L. Ochs , in a field survey on November 10 , 19 98 , do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner 12 4 7 R 9 10 11 points mentioned in lines 1 and 2 above were in conformance with regulations and rules 5 therefore as required in the current manual of survey instructions of the United States 15 18 17 16 14 13 6 Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a 7 23 24 19 20 21 22 Ŷ Decree of a Court of Law; established, re-established, monumented, re-monumented, 9 recovered, found as expressed below.

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Southeast Corner, Section 34, Sheridan Township, Newaygo County, Michigan.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1837 30" Pine N57°E 44 Links (29.04')#1 18" Pine N62°W 30 Links (19.8')#2 Northeast Corner, Section 3, T11N R14W, West 50 Links (33')#10

Lyle S. Shepherd R.L.S. #503 Book 26, Page 10 April 21, 1914 Measured 50 Links (33') from the Northeast Corner of Section 3, T11N R14W to the Southeast Corner of Section 34, T12N R14W.

Newaygo County Road Commission Sheet 11/2" Pipe 10" Apple S27°E 73.7' #3 14" Apple S40°E 56.3' #4 4" Elm N31°E 46.4' #5

Delos G. Anderson (County Surveyor) Book A, Pages 199 and 200 August 14, 1896 Measured 39.77 Chains (2624.82') from the East One Quarter Corner to the Southeast Corner of Section 34.

30

31

10

11

29

32

28

33

27

34

Norman L. Ochs R.L.S. #22439 June 11, 1997 Drawing Number 97156B Found 11/2" Iron Pipe. Replaced with 1/2" Rod and cap 10" Black Gum N33°E 19.76' #6 10" Red Pine S17°E 40.07' #7 10" Red Pine S63°W 66.63' #8 Fence Post N14°E 31.30' #9

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found $\frac{1}{2}$ Rod and cap #22439 on top of broken glass and crockery 2' \pm below grade, 1 foot \pm North of the centerline of the East and West dirt road. The centerline of the dirt drive going South is 20 feet \pm West and the fence going North is 6 feet \pm East. The condition of the recorded witnesses are: #1 thru #5 gone, #6 thru #9 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed 1/2" Rod and cap #22439 and set a 4" diameter Harrison cast iron monument 23" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner

as a substantial marker for the section corner and is accepted	as a careful and faithful reestablishment of the original corner.
10" Black Gum (blazed) N33°E 19.76' Found spike in Northwe 10" Red Pine (blazed) S17°E 40.07' Found spike in West side 10" Red Pine (blazed) S63°W 66.63' Found spike in Northerly Corner Fence Post N14°E 31.30' Found "Advanced Survey ar ½" Iron and cap #30389 West 27.33'	of tree, #7 side of tree, #8 I. OCHS AMD SURVEYOR SURVEYOR 22/139
Signed by //Olman & Ocho	Date <u>December 18, 1998</u>
Norman L. Ochs	OKAJ OTALO
Surveyor's Michigan License No22439	Form approved by Michigan State Board of Land Surve that 12, 1275 Revised May 14, 1975
Approved by Peer Review Group on	Revised Jan., 1983
Norman L. Ochs, County Representative.	
7. 4.0.	