MAR 02 1999

NEWAYGO COUNTY REGISTER OF DEEDS

1998 Newaygo County Remonumentation Project LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE 9 FEB 17 PM 3 36 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo (County)	Located in:	Corner Code #	Linds W.	1. Brown
1. Public Land Survey	T <u>12N</u> R <u>14W</u> T R T R	K-4	vol. $oldsymbol{2}$	181
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR	R	egister of Deeds Stamp	& File Number
concereby certify that under requipoints mentioned in lines 1 and 2 inherefore as required in the curred performent of the Interior, Bured and/or that the corner possible of the conformance with the rules of Decree of a Court of Law; estable recovered, found as expressed be	, in a field survey on	a. of 1970, the corner egulations and rules of the United States decree of a Court of 5 above were in Surveyors or by a ed, re-monumented,	1 2 - 6 - 5 - 4 - 3 4 - 7 - 8 - 9 - 5 6 - 18 - 17 - 16 - 7	22 + 23 + 24 -
	ection 11, Sheridan Township,		20	
A. DESCRIPTION OF OF	RIGINAL MONUMENT AND	ACCESSORIES AND/O	R SUBSEQUENT RES	TORATION:

G.L.O. John Mullett 1838 18" Beech N62°E 17 Links (11.22')#1 8" Beech S24°W 17 Links (11.22')#2

Delos G. Anderson (County Surveyor) Book A Pages 161 and 162 March 30, 1895 Wagon Hub Iron Stake 24" long

Newaygo County Road Commission Sheet Monument Box in pavement

William M. Jacques (County Surveyor) Book B Pages 42 and 43 April 22, 1910 Iron Hub and Axle with broken glass around.

PED LAND

William Fries, Jr. R.L.S. #30389 LCRC #900 February 22, 1989 Found 1" Iron in a Monument Box 1 foot West of the occupied centerline of a North and South road and in a tree row to the West and East. 30" Basswood N43°E 68.76' #3 3½" X 5½" Sign Post S88°E 69.01' #4 Power Pole S48°W 69.32' #5

Concrete Monument with cap #30389 West 50.10' #6

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1" X 24" Rod, Wagon Hub with 2½" diameter top (3¾" diameter bottom and 12" long) and broken glass in monument box. The centerline of the North and South bituminous road is 1 foot ± East and on line ± with East and West tree \ brush row. The condition of the recorded witnesses are: #1 and #2 gone, #3 thru #6 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rod, Wagon Hub, broken glass and set a 23/2" X 20" Harrison cast iron monument marked "County Survey" in new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

36" Ash N48°E 68.93' Found nail with tag "Advanced Survey & Map", set new spike with tag #22439 in West side of tree. #3 4" X 6" Sign Post S86°E 69.07' Found P.K. nail with tag "Advanced Survey & Map" in North side of post. #4 Power Pole S50°W 69.18' Found P.K. nail with tag "Advanced Survey & Map" in Northwe

3" diameter concrete monument West 49.97' with cap #303	ed agrae) g mgb iii iaoi ti mesteti?	/ side of pole. #3
o diameter concrete monument west 49,97 With cap #303	89. #6	
Power Pole S83°E 45.53' Set spike with tag #22439 in South	h side of pole	William
\mathcal{A}/\mathcal{A}		SEE TE OF
Signed by Moman L. Ocho	Date October 15, 1998	A Localita
Norman L. Ochs		F. NOR
Surveyor's Michigan License No. 22439	Form approved by Michigan State Day	27/
	Form approved by Michigan State Board	or canor surveyors,
Approved by Peer Review Group onOctober 22, 1998		Revised K
Norman L. Ochs, County Representative.		Revise
Shariff and the state of the st		22
11) Y (4)		M 5 m 22
77.2.0.		The Constitution of the Co