

WAR 02 1999

SECTION

## 1998 Newaygo County Remonumentation

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PM 3 36

For corners in Newaygo (County)	Located in:	Corner Code #	Se	nde III. Spou
1. Public Land Survey	T <u>12N</u> R <u>14W</u> TR TR	<u>K-10</u>	vol. 2	186
Property Controlling     in Section     Miscellaneous     Property in Sec.	STR STR STR		Register of Deeds Stan	np & File Number
4. Lot No, Recor 5. Private Claims	ded Plat		2 6 + 5 + 4	G H I J K L M
I, Norman L. Ochs do hereby certify that under requ points mentioned in lines 1 and 2 therefore as required in the curre	irements of P. A. 74, Michigan F above were in conformance with	P.A. of 1970, the corner n regulations and rules	3 4 7 8 9 9	10 - 11 - 12 -
Department of the Interior, Bures Law and/or that the corner poi conformance with the rules of Decree of a Court of Law; establ recovered, found as expressed b	au of Land Management or by a nts mentioned in lines 3, 4 a the Michigan Board of Land ished, re-established, monume	a decree of a Court of nd 5 above were in il Surveyors or by a	6 - 18 - 17 - 16 · 7 8 - 19 - 20 - 21 9	15 14 13 -
Note: Not more than 4 or recorded on this c		town and range, may be	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	+++++
East One Quarter Corner, Se	ection 26, Sheridan Townshi	p, Newaygo County, Michiga	,	

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Mullett 1839 18" Hemlock Corner

M. K.O.

Delos G. Anderson (County Surveyor)
Book A Page 332 January 7 and 8, 1902
14" White Oak N62°20'W 18½ Links (12.21)#1

Norman L. Ochs R.L.S. #22439 June 25, 1980 Found Railroad spike in monument box Power Pole N85°E 79.00' #8 Newaygo County Road Commission Sheet Iron Telephone Pole N55°W 28.9' #3 Power Pole N79°E 78.6' #4 Telephone Pole S84°E 33.1' #5

Patrick A. Salisbury R.L.S. #13594 LCRC #7 December 12, 1971 Set corner from angle and distance from Northeast Corner Section 26 and angle and distance from Southeast Corner Section 26. Set Railroad spike - 1.20 feet West of centerline of road - on South edge of ditch going East - 6 feet South of fence East.

Telephone Pole N15°W 169.85' #6 Telephone Pole S20°W 98.09' #7 Power Pole N85°E 79.00' #8

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found Railroad spike in monument box in centerline of North and South bituminous road. The centerline of ditch to East is 2 feet North and on line with edge of woods extending 660 feet from the West. The condition of the recorded witnesses are: #1 thru #3 gone, #4 good condition, #5 thru #8 gone.

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Railroad spike and set a 2%" dlameter Harrison cast iron monument 20" long marked "County Survey" in monument box as a substantial marker for the quarter corner and is accepted as a careful and faithful reestablishment of the original corner.

the original corner.	- NAMMANI.
Power Pole N87°E 79.19' Found spike in South side of pole. #4 Power Pole S10°E 331.74' Set spike and tag in East side of pole.  ½" X 18" Rod and cap #22439 S64°W 38.89' 6" below grade in North  ½" X 18" Rod and cap #22439 N27°W 62.48' 6" below grade in North  Signed by	h and South farm lane.
Norman L. Ochs	22439 oproved by Michigan State Board of Land Surgress Jan 28, 197
Approved by Peer Review Group on <u>December 8, 1998</u> Norman L. Ochs, County Representative.	William 1983