MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYGO OCULT REGISTER OF DECI LINDA M. DROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MAN 6 PM 12

For corners in Newaygo (County)	Located in:	Corner Code#	O.) (1)))) (1) (1) (1) (1) (1) (1) (1) (1
1. Public Land Survey	T <u>13N</u> R <u>11W</u> T R T R	<u>K-11</u>	vol. 2	96
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp & F	ile Number
4. Lot No, Recor 5. Private Claims	ded Plat		A B C D E F G H 2 - 6 + 5 + 4 + 3	I J K L M
I, Norman L. Ochs , in a field survey on September 17, 19, 97, do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:			3 4 7 8 9 10 5 6 18 17 16 15 7	
			$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	
Note: Not more than 4 c recorded on this co	orners, all in the same tow ertificate.	n and range, may be	e 10 30 23 28 27 11 12 31 + 32 + 33 + 34	++++
Northwest Corner, Section 36	Rig Prairie Township, Newayo	o County Michigan		

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. James H. Mullett 8" Beech N31°E 44 Links (9.24')#1 10" Pine S29°E 39 Links (25.74')#2

Newaygo County Road Commission Sheet Axle Shaft 24" Black Oak Northeast 50.5' #5 24" Maple S50°E 84.9' #6 7" Elm \$33°E 25.74' #3 6" Oak N25°W 31.35' #4

Newaygo Engineering and Survey Company April 24, 1983 Drawing Number 83060AC Found 5/8" Rod 24" Black Oak N57°E 50.63' #5 24" Maple S55°E 86.58' #6 Power Pole S85°W 37.99' #7

Ralph A. Smith R.L.S. #3421 Witness Book Number 2 Page 49 Iron 7" Elm S33°±E 25.74' #3 6" Oak N25°±W 31.35' #4

Newaygo Engineering and Survey Company 1978 Drawing Number 77158B Found 1/2" Rod 24" Black Oak N57°E 49.39' #5 24" Maple S55°E 85.17' #6 Power Pole S85°W 37.65' #7

OVER &

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found Axle Shaft (50" long - measured 1/2" at top - measured 5/8" at bottom - measured 1/2" at center) and found crockery 20" under road bed. The centerline of gravel road going East is 3 feet South and in the centerline of North and South gravel road. The condition of the recorded witnesses are: #1 thru #4 gone, #5 thru #8 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Axle Shaft and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

42" Black Oak N53°E 50.71' Found spike in Southeast side of tree. #5 48" Maple S55°E 86.61' Found spike in Northeast side of tree. #6 Power Pole S76°W 37.98' Found nail in Southeast side of pole. #7 Power Pole N33°E 72.95' Found nail in West side of pole. #8 Date_ Signed by

October 10, 1997 Norman L. Ochs

Surveyor's Michigan License No. Form approved by Michigan State Board &

Approved by Peer Review Group on October 14, 1997 Norman L. Ochs, County Representative.



A. Description (cont.)

Newaygo Engineering and Survey Company January 19, 1996 Drawing Number 96013B Found 5/8" Rod Power Pole N30°E 72.93' #8 24" Black Oak N57°E 50.68' #5 24" Maple S55°E 86.60' #6 Power Pole S85°W 38.00' #7

John Kistler and Associates William Byl Undated field notes Found Axle