MAR 1 9 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. DROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MAR 6 PM 12 36

n

ß

For corners in Newaygo (County)	Located in:	Corner Code #	Lin	de M. Oscare
Public Land Survey	T <u>13N</u> R <u>11W</u> T R T R T R	K-13	vol. 2	98
Property Controlling     in Section	STR STR			
Miscellaneous     Property in Sec.	STR STR		Register of Deeds Stan	np & File Number
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curricular Department of the Interior, Bure Law and/or that the corner po conformance with the rules of Decree of a Court of Law; estab recovered, found as expressed by	_, in a field survey on <u>Septem</u> .irements of P. A. 74, Michigan P. 2 above were in conformance with ent manual of survey instructions au of Land Management or by a ints mentioned in lines 3, 4 an the Michigan Board of Land lished, re-established, monumen	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a sted, re-monumented,	1	G H I J K L M  3 - 2 - 1 -  10 - 11 - 12 -  15 - 14 - 13 -  22 - 23 - 24 -  27 - 26 - 25 -
recorded on this c		own and range, may b	11	+ 34 + 35 + 36 -
Southwest Corner, Section 3	86, Big Prairie Township, New	aygo County, Michigan.	13	

## A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1837 8" Pine N62°E 33 Links (21.78')#1 8" White Oak N46°W 54 Links (35.64')#2

Newaygo County Road Commission Sheet 5" Twin Black Oak N30°W 61.6' #3 4" Twin Black Oak S48°E 63.0' #4 Norman L. Ochs R.L.S. #22439 LCRC #582 May 17, 1983 Found ¾" Pipe 1" Pipe, Northwest Corner, Section 1, T12N R11W, West 18.06' #5 Power Pole N20°E 118.28' #6 8"-10" Twin Black Oak N30°W 61.73' #3 14" Black Oak S48°E 62.83' #4

SAND

## B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found %" Pipe 45" long with crockery around it and a wood stake. The centerline of the North and South gravel road is 9 feet West and the centerline of gravel road going East is 4 feet North and in the centerline of two-track going West. The condition of the recorded witnesses are: #1 and #2 gone, #3 stump, #4 thru #6 good condition.

## C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed ¾" Pipe and wood stake and set a 4" diameter Harrison cast iron monument 20" long, with crockery around it, marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Black Oak Stump N32°W 61.71' center. #3 22" Black Oak S42°E 62.8' Found spike in Northeast side 34" Pipe West 18.00", Northwest Corner, Section 1, T12N Power Pole N24°E 118.22' Found spike in Northwest side	R11W.#5 of pole.#6			
10" White Pine N20°W 74.56' Set spike and tag in Southwest side of tree.				
Signed by Mormon L. Ochs	Date <u>October 10, 1997</u>			
Norman L. Ochs				
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971			
Approved by Peer Review Group on October 14, 1997	Revised May 14, 1975 Revised Jan., 1983			
Norman L. Ochs, County Representative.				
$M \mathcal{P} \mathcal{O}$	NORMAN			
7/, A, O.				
, , , , , , , , , , , , , , , , , , ,	## L OCHS **			