

1996 Newaygo County Remonumentation Project

NEWAYGG COUNTY REGISTER OF DEEDS LINDA M. BROWN

MAY 28 1997

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'97 FEB 12 PM 4 45

COMMISSION FILING REQUIREMENT OF ACT 74, MICH. P.A. 197			P.A. 1970	9/15	IZ PII	4 45
For corners in Newaygo (County)	Located in:	Corner Code #		Lind	am. L	hown
1. Public Land Survey	T <u>13N</u> R <u>12W</u> T R T R	C-6	VOL. 1	PAGE	240	
Property Controlling in Section Miscellaneous	6 TR 6 T R 6 T R		TO THE SECOND	TAUL	~ 10	
Property in Sec.	5TR		gister of Deeds S	tamp & File	Number	_
4. Lot No, Recorded 5. Private Claims	l Plat	· · · · · · · · · · · · · · · · · · ·	2 _ 0 _ 0	C U E F		K L M
I, <u>Norman L. Ochs</u> in a do hereby certify that under requiren points mentioned in lines 1 and 2 abo	nents of P. A. 74, Michigan P ove were in conformance with	A. of 1970, the corner requiations and rules	5	 		
therefore as required in the current r Department of the Interior, Bureau o	f Land Management or by a	a decree of a Court of	7	1716		- 3
Law and/or that the corner points conformance with the rules of the Decree of a Court of Law; establishe recovered, found as expressed below	e Michigan Board of Land ed, re-established, monume	Surveyors or by a	9			
Note: Not more than 4 cor recorded on this cer		town and range, may be	10 -30-	- - -	<u> </u>	
West One Quarter Comer, S	Section 17, Everett To	wnship, Newaygo County, M	13 LLL ichigan	_ل_لبا	<u> </u>	

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. J.H. Mullett 1837 8" Tamrack N33°W 34 Links (22.44')#1 6" Tamrack N68°E 7 Links (4.62')#2

County Surveyor Office - From Drain Book Gas Pipe Southeast Corner Building Northwest 55,4' #3 Southwest Corner Building Northwest 61.1'#4

Norman L. Ochs RLS #22349 December 12, 1989 Found "T" Iron - removed and set a 4" diameter cast iron Harrison Monument marked "County Surveyor" Power Pole S36°W 26.37' #5 Southeast Corner of New Garage N20°W 83.83' #9 5" Elm N45°F 21 75' #10 6" Elm S20°E 62.30' #11

Lyle S. Shepherd RLS #503 September 1915 Book B Page 71 Set wooden stake

Sammy S. Barnett RLS #16923 LCRC #305 December 20, 1973 Set "T" Iron Power Pole S36°W 26.63' #5 Gate Post N64°W 6.10' #6 Gate Post N82°E 10.42' #7 Southeast Corner Garage N10°W 57.8' #8

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found nothing. Lyle S. Shepherd set a wooden stake 1/2 way and on line between Northwest Corner and Southwest Corner of Section 17 in 1915 and Sammy S. Barnett set "T" Iron ½ way and on line between Northwest Corner and Southwest Corner of Section 17 in 1973. I reestablished the corner by 2 previous witnesses we found and the condition of the recorded witnesses are: #1 thru #4 gone, #5 good condition, #6 thru #8 gone, #9 good condition, #10 and #11 gone. The Harrison monument we set in 1989 was removed during cleanout of a county drain.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Re-set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner. MICHIGA

Power Pole S36°W 26.37' Tag in East side of pole. #5 Southeast Corner Garage N20°W 83.83' #9 8" Walnut N70°W 38.88' Spike in South side of tree. 12" Poplar S22°E 31.40' Spike in West side of tree. Centerline of ditch East 7.0

22439

September 17, 1996

Centerline of ditch South 5.0'

Surveyor's Michigan License No.

Approved by Peer Review Group On

Signed by Norman L. Ochs Date September 13, 1996

Form approved by Michigan State Board of Land Surveyors, 381

Revised May 14, 1975 Revised Jan., 1983

D F

NORMAN

L. OCHS

LAND SURVEYOR

22439

LAND

Norman L. Ochs, County Representative.