

MAR 0 8 1999

SECTION

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PM 3 38

1. Public Land Survey T 13N R 12W E-3 T R T R	vol. 2	224
T 5	104. 10	443
2. Property Controlling S T R INSection S T R 3. Miscellaneous S T R Property in Sec. S T R R	egister of Deeds_St	amp & File Number
4. Lot No, Recorded Plat	5 - 18 - 17 - 1	F G H I J K L M 4 - 3 - 2 - 1 - 1 9 - 10 - 11 - 12 - 1 6 - 15 - 14 - 13 - 1 1 - 22 - 23 - 24 - 1
Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Southeast Corner, Section 5, Everett Township Newaygo County, Michigan.	10 - 30 + 29 + 2 11	8 - 27 - 26 - 25 - 3 - 34 - 35 - 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. J.H. Mullett 1837 12" Beech S64°E 14 Links (9.24')#1 8" Beech N03°E 13 Links (8.58')#2

M. L.O.

William M. Jacques (County Surveyor)

November 4, 1904 Book B, Pages 10 and 11

Found tree. Set new stake with broken glass placed around post.

20" Pine Stump S34°E 51 Links (33.66')#3

William M. Jacques (County Surveyor) November 7, 1904 Book 10 Page 18 Pine Stake with broken glass 20" Pine Stump S341/2°E 34' #3 24" Pine Stump N51°W 43' #4

Lyle S. Shepherd R.L.S. #503 Book 37A Page 4 May 13, 1922 18" Pine Stump \$73½°W 64.5' #5 22" Pine Stump \$32¾°E 35.5' #3

OVER ♥

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 4" diameter Harrison cast iron monument marked "County Surveyor" in 8" diameter monument box with cover on line ± with the centerline of the gravel road going South. The centerline of the East and West bituminous road is 3 feet North and the centerline of the bituminous road going Northwest (extended Southeast) is 18 feet East. The condition of the recorded witnesses are: #1 thru #5 gone, #6 good condition, #7 thru #9 gone, #10 thru #12 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

•	The state of the s
Northwest Corner Main Building of Church (at brick corner)	\$50°E 122.14' #6
Power Pole N20°E 106.45' Found spike in Westerly side of	
Guy Pole N53°W 52.37' Set spike with tag #22439 in South	
Power Pole N47° \$ 45.58' Found P.K. nail in Southeasterly s	side of pole. #12
Signed by Morman L. Ocho	Date December 4, 1998
Norman L. Ochs	
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group On	Revised May 14, 1975 Revised Jan., 1983

NORMAN

L: OCHS

LAND

SURVEYOR

22439

A. Description (cont.)

Ralph A. Smith R.L.S. #3421 Book 37A Page 4 June 7, 1955 Axle Shaft Northwest Corner Church S55°E 122.6'#6 Power Pole N42°E 55.15' #7 Power Pole N44°W 60.4' #8

Patrick A. Salisbury R.L.S. #13594 and Paul Paquette R.L.S. #16938 "Amity Acres" Plat Southeast Corner of Plat February 18, 1969 Recorded in Liber 8 of Plats, Pages 42 and 43

Patrick A. Salisbury R.L.S. #13594 August 28, 1973 Drawing Number 73148AC Found Axle Shaft Northwest Corner Church S55°E 122.6' #6 Telephone Pole S60°W 36.52'#9 Power Pole N23°E 106.33' #10

Norman L. Ochs R.L.S. #22439
Drawing Number 76053AC June 10, 1976
Found Axle Shaft
Iron North 26.20' #13
Northwest Corner Church S55°E 122.6' #6
Telephone Pole S60°W 36.52' #9
Power Pole N23°E 106.33' #10

Norman L. Ochs R.L.S. #22439 Drawing Numbers 83034B and 83036B April 21, 1983 Found Axle Shaft Northwest Corner Church S55°E 122.60' #6 Telephone Pole S60°W 36.52' #9 Power Pole N23°E 106.33' #10

Stanley H. Shackelford R.L.S. #30100
February 1987 LCRC #772
Power Pole N20°E 106.50' #10
Power Pole N44°W 51.80' #11
Northwest to the Northeast Corner of Church S55°E 122.60' #6

Norman L. Ochs R.L.S. #22439
December 12, 1989 LCRC #939
Found Axle Shaft in monument box. Removed and set 4" diameter Harrison cast iron monument marked "County Surveyor"
Guy Pole N44°W 52.06' #11
Power Pole N50°E 44.55' #12
Power Pole N20°E 106.40' #10
Northwest Corner Church S55°E 107.13' #6

SURVEY & REMONUMENTATION

MAR 02 1999

SECTION