NEWAYGO COUNTY REGISTER OF DEEDS

1998 Newaygo County Remonumentation Project

LINDA M. BROWN

MAR 0 2 1999

LAND CORNER RECORDATION CERTIFICATE '99 FEB 17 PM 3 39 FILING REQUIREMENT of Act 74, Mich. P.A. 1970

For corners in Newaygo (County)	Located in:	Corner Code#	Linda M.	Drown
1. Public Land Survey	T <u>13N</u> R <u>12W</u> T R T R	F-7	VOL. $oldsymbol{2}$	226
Property Controlling in Section Miscellaneous Property in Sec.	TR STR STR STR		Register of Deeds Stamp & Fi	le Number
do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curr Department of the Interior, Bure Law and/or that the corner po conformance with the rules of Decree of a Court of Law, estable recovered, found as expressed by	in a field survey on November uirements of P. A. 74, Michigan P. 2 above were in conformance with ent manual of survey instructions au of Land Management or by a ints mentioned in lines 3, 4 and the Michigan Board of Land dished, re-established, monument below:	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a ted, re-monumented,	A B C D E F G H 2 - 6 - 5 - 4 - 3 - 3 3 - 1 - 1 - 16 - 15 - 7 8 - 19 - 20 - 21 - 22 - 9 10 - 30 - 29 - 28 - 27 - 11	11 - 12 - - 14 - 13 - - 23 - 24 -
North One Quarter Corner, S	Section 21, Everett Township I	Newaygo County, Michigan.	12 31 + 32 + 33 + 34 -	35 + 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O.: J.H. Mullett 1837 6" Beech S011/2°W 3 Links (1.98')#1 10" White Oak N34°E 26 Links (17.16')#2

Ralph A. Smith R.L.S. #3421 October 18, 1951 Book 70A, Page 44 Found stone with rotten stake under it. Set 1/2" Rod. Power Pole N05°W 68.6' #3 10" Black Oak S80°E 151.9' #4

Patrick A. Salisbury R.L.S. #13594 1972 Found nothing. Reset corner by Ralph A. Smith's section breakdown. Set a 11/2" Pipe X 2 feet long. Power Pole N05°W 68.58' #3 20" Maple S20°W 113.79' #5 22" Black Oak S80°E 154.33' #4

OVER &

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 4" diameter Harrison cast iron monument (too corroded to read) 6 inches ± below grade on line ± with the centerline of the East and West gravel road and on line ± with the fence going North and on line ± with the woods line going South. The condition of the recorded witnesses are: #1 and #2 gone, #3 good condition, #4 stump, #5 gone, #6 and #7 good condition, #8 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 4" diameter Harrison cast iron monument 36" long as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original or

and the state of t	가 (: CI .	
Power Pole N05°E 68.32' Set spike with tag #22439 in W	Vest side of note #3	
22" diameter Stump S76°E 154' ± to center. #4	rost side of pole, no	
1/2" Rerod North 33,07' #6		
Power Pole S40°W 39.00' Found nail in Easterly side of p	nole #7	
10" White Pine (blazed) S40°E 59.05' Set spike with tag #	HOOLE, #1	
4" - 6" - 8" Triple Maple (blazed) N58°W 61.12' Set spike	with tan #22439 in Easterly side of tree	
\mathcal{N} $\mathcal{V} \cap \mathcal{V}$	Mar and meeting and of thee.	
Signed by //DMan & Ochs	Date December 4, 1998	
Norman L. Ochs	<u> </u>	
Surveyor's Michigan License No. 22439	Form approved by Michigan State Board of Land Surveyors, Jan.	28 1971
	Revised May	14 197
Approved by Peer Review Group On December 22, 1998	OF MICHIGAN Revised J	-
Norman L. Ochs, County Representative.		,

NORMAN L. OCHS RVEYOR LAND

A. Description (cont.)

Norman L. Ochs, R.L.S. #22439 June 21, 1978 Found 1½" Pipe Power Pole N05°W 67.83' #3 20" Maple S76°W 113.36' #5 22" Black Oak S80°E 154.33' #4 ½" Rod North 33.06' #6

Drawing Number 78110B

Norman L. Ochs, R.L.S. #22439

December 3, 1987 LCRC #817

Found 1½" Pipe. Removed and set a 4" diameter Harrison cast iron monument 36" long marked "County Surveyor" Power Pole N05°W 68.33' #3

22" Maple S76°W 113.83' #5

Power Pole S40°W 39.03' #7

6" Apple N40°E 57.28' #8

William Fries, Jr. R.L.S. #30389 1994 Found cast iron monument Power Pole N05°W 86.33' #3 22" Maple S76°W 113.83' #5 Power Pole S40°W 39.93' #7 8" Apple N40°E 57.28' #8



SURVEY & REMONUMENTATION

MAR 02 1999

SECTION