## SURVEY & REMONUMENTATION

For corners COMMISSION

Surveyor's Michigan License No.

Accepted by Peer Review Group on November 3, 1994 Norman L. Ochs, County Representative. M.O.

Newaygo

APR 2 4 1995 LAND CORNED RECORDS TO STATE OF THE PROPERTY OF T

Located In:

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 VOL 001 PAGE 108

Corner Code ##

1. Public Land Survey T 13N <sub>R</sub> 12W J-13	
	NEWAYOD COUNTY.
T R	REGISTER OF DEEDS MARLENE TOOGOOD
TR	MAKEENE 100G00D
2. Property Controlling S T R	'95 MAR 14 PM 3 56
3. Miscellaneous S T R	Register of Deeds Stamp & File Number
Property in Sec. S T R	Marlene lougood
4. Lot No, Recorded Plat	A B C D E F G H I J K
5. Private Claims	2 6 5 4 3 2
	3
Norman L. Ochs in a field survey on October 29 , 19	94 \$ 7 8 9 10 11
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mein lines 1 and 2 above were in conformance with regulations and rules therefore as required	
current manual of survey instructions of the United States Department of the Interior, Bureau of Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,	of Land
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Dec	cree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, for expressed below:	and as
NOTE: Not more than 4 corners, all in the same town and range, may be recorded	
on this certificate.  S. 1/4 Corner, Section 35, Everett Twp., Newaygo	12 31 32 33 34 35 CO. MI 13
A. Description of original monument and accessories and/or subsequent restoration	
G.L.O. John Hodgson 1837 Robert A. Griffin R.L.S. #1	
8" W. Oak S37 1/2"W 200 lks. (132') #1 Set 5" Sq. Reinforced Conc. 6" R. Pine N21"E 80.45' #3	. Post w/brass disk (See other side for measured distances)
W.S. Herrill (Co. Surveyor) 5"x7' Cedar Post East 2.20'	* #4 N. 1/4 Cor, Sec. 2,
Book A Page 62 March 10, 1882 6" R. Pine N38"W 106.35' \$5 6" B. Oak South 176 lks. (116.16') \$2	5 T12N R12N East 4.62 #6
Measured 40.23 chains (2655.18 feet) from the S. 1/4 Cor. to the SW. Cor.	. of Sec. 35. Measured 39.88 Chains (2632.08
feet) from the S. 1/4 Cor. to the C. 1/4 Cor. of Sec. 35. Measured 40.23	Chains (2655.18 feet) from the S. 1/4 Cor.
to the S.R. Cor. of Sec. 35.  B. Description of corner evidence found and/or method applied in restoring or rees	stablishing corner:
b. Description of corner evidence round and/or method applied in restoring or rees	orasioning commen
B. Description of comer evidence found and/or method applied in restoring of feet	
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei	inforced Conc. Post w/ brass cap. I, measure
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SR. Cor. to the S. 1/4 Cor. of Sec. 35 and measured	inforced Conc. Post w/ brass cap. I, measure d 2653.56 feet from the S. /1 4 Cor. to the
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei	inforced Conc. Post w/ brass cap. I, measure d 2653.56 feet from the S. /1 4 Cor. to the
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SR. Cor. to the S. 1/4 Cor. of Sec. 35 and measured	inforced Conc. Post w/ brass cap. I, measure d 2653.56 feet from the S. /1 4 Cor. to the
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SR. Cor. to the S. 1/4 Cor. of Sec. 35 and measured	inforced Conc. Post w/ brass cap. I, measure d 2653.56 feet from the S. /1 4 Cor. to the
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SR. Cor. to the S. 1/4 Cor. of Sec. 35 and measured	inforced Conc. Post w/ brass cap. I, measure d 2653.56 feet from the S. /1 4 Cor. to the
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SR. Cor. to the S. 1/4 Cor. of Sec. 35 and measured	inforced Conc. Post w/ brass cap. I, measure d 2653.56 feet from the S. /1 4 Cor. to the
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SE. Cor. to the S. 1/4 Cor. of Sec. 35 and measured SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the one, #3 Thru #6 Good Condition.
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SR. Cor. to the S. 1/4 Cor. of Sec. 35 and measured	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the one, #3 Thru #6 Good Condition.
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SR. Cor. to the S. 1/4 Cor. of Sec. 35 and measured SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go.  C. Description of monument for corner and accessories established to perpetuate	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the one, #3 Thru #6 Good Condition.
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SR. Cor. to the S. 1/4 Cor. of Sec. 35 and measured SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go.  C. Description of monument for corner and accessories established to perpetuate accepted Robert A. Griffin's 5" Sq. Reinforced Conc. Post as a substantia	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the one, #3 Thru #6 Good Condition.  locating the position of the corner:
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SE. Cor. to the S. 1/4 Cor. of Sec. 35 and measured SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go. Cor. Description of monument for corner and accessories established to perpetuate accepted Robert A. Griffin's 5" Sq. Reinforced Conc. Post as a substantial accepted as a careful and faithful reestablishment of the original corner 10" Oak S60°E 33.80' Spike in South side of tree	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the one, #3 Thru #6 Good Condition.  locating the position of the corner:
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SR. Cor. to the S. 1/4 Cor. of Sec. 35 and measured SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go and \$2 Go and \$2 Go are selected as a careful and faithful reestablishment of the original corner 10" Oak \$60°E 33.80' Spike in South side of tree \$10" Pine N21°E 80.45' Pnd. spike in West side of tree \$3	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the ome, #3 Thru #6 Good Condition.  locating the position of the corner:  All marker for the section corner and is NORMAN
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SE. Cor. to the S. 1/4 Cor. of Sec. 35 and measured SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go and Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go are correctly as a substantial accepted Robert A. Griffin's 5" Sq. Reinforced Conc. Post as a substantial accepted as a careful and faithful reestablishment of the original corner 10" Oak S60°E 33.80' Spike in South side of tree 10" Pine N21°E 80.45' Fnd. spike in West side of tree \$3 Cedar Post East 2.20' (Face) \$4 12" Pine N38°W 106.35' Fnd. spike in NE. side of tree \$5	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the one, #3 Thru #6 Good Condition.  locating the position of the corner:
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SE. Cor. to the S. 1/4 Cor. of Sec. 35 and measured SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. Post as a substantial accepted as a careful and faithful reestablishment of the original corner 10" Oak S60°E 33.80' Spike in South side of tree 10" Pine M21°E 80.45' Fnd. spike in West side of tree \$3 Cedar Post East 2.20' (Face) \$4 12" Pine M38'W 106.35' Fnd. spike in ME. side of tree \$5 Conc. Mon. w/brass cap (M. 1/4 Cor. Sec. 2, T12M R12W) East 4.62' \$6	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the one, #3 Thru #6 Good Condition.  locating the position of the corner:  at marker for the section corner and is  NORMAN L. OCHS LAND SURVEYOR
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SE. Cor. to the S. 1/4 Cor. of Sec. 35 and measured SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go and Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go are correctly as a substantial accepted Robert A. Griffin's 5" Sq. Reinforced Conc. Post as a substantial accepted as a careful and faithful reestablishment of the original corner 10" Oak S60°E 33.80' Spike in South side of tree 10" Pine N21°E 80.45' Fnd. spike in West side of tree \$3 Cedar Post East 2.20' (Face) \$4 12" Pine N38°W 106.35' Fnd. spike in NE. side of tree \$5	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the one, #3 Thru #6 Good Condition.  locating the position of the corner:  at marker for the section corner and is  NORMAN L. OCHS LAND SURVEYOR
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SE. Cor. to the S. 1/4 Cor. of Sec. 35 and measured SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. Post as a substantial accepted as a careful and faithful reestablishment of the original corner 10" Oak S60°E 33.80' Spike in South side of tree 10" Pine M21°E 80.45' Fnd. spike in West side of tree \$3 Cedar Post East 2.20' (Face) \$4 12" Pine M38'W 106.35' Fnd. spike in ME. side of tree \$5 Conc. Mon. w/brass cap (M. 1/4 Cor. Sec. 2, T12M R12W) East 4.62' \$6	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the one, #3 Thru #6 Good Condition.  locating the position of the corner:  al marker for the section corner and is  NORMAN L. OCHS LAND SURVEYOR SURVEYOR
In October, 1994, I, Norman L. Ochs, found Robert A. Griffin's 5" Sq. Rei 2653.59 feet from the SE. Cor. to the S. 1/4 Cor. of Sec. 35 and measured SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. of Sec. 35 and Condition of recorded witnesses are: \$1 and \$2 Go SW. Cor. Post as a substantial accepted as a careful and faithful reestablishment of the original corner 10" Oak S60°E 33.80' Spike in South side of tree 10" Pine M21°E 80.45' Fnd. spike in West side of tree \$3 Cedar Post East 2.20' (Face) \$4 12" Pine M38'W 106.35' Fnd. spike in ME. side of tree \$5 Conc. Mon. w/brass cap (M. 1/4 Cor. Sec. 2, T12M R12W) East 4.62' \$6	inforced Conc. Post w/ brass cap. I, measured 2653.56 feet from the S. /1 4 Cor. to the one, #3 Thru #6 Good Condition.  locating the position of the corner:  at marker for the section corner and is  NORMAN L. OCHS LAND SURVEYOR 22439

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197.

REVISED JAN., 198

A. Description..... (Continued)

Robert a. Griffin R.L.S. #13584 June 29, 1964

He reestablished the location of this corner equal distance and on a straight line between the SE. Corner and the SW. Corner of Sec. 35 and measured 2652.84 feet from the S.W. Cor. to the S. 1/4 Cor. of Sec. 35 and measured 2652.84 feet from the S. 1/4 Cor. to the S.E. Cor. of Sec. 35.

Newaygo Engineering and Survey Co. May 14, 1979 Found Conc. Mon. 6" R. Pine N21'E 80.45' #3 Cedar Post East 2.20' #4 6" R. Pine N38'W 106.35' #5

Measured 2632.54 feet from the S. 1/4 Corner to the C. 1/4 Corner, Sec. 35. Measured 2654.87 feet from the S. 1/4 Corner to the S.E. Corner of Sec. 35. Measured 2653.54 feet from the S. 1/4 Corner to the S.W. Corner, Sec. 35. Measured 4.65 feet from the S. 1/4 Corner of Sec. 35 East to the N. 1/4 Corner of Sec. 2, T12N R12W.