HEWAYGO COUNTY VICTED OF DEEDS

	1993 NEWAYGO~COUN	TY REMONUMENTATION PR		OF BELLOO
	LAND COR	NER RECORDATION CERT	TFICATE MARLENE	TOOGOOD
For corners in	Filing Requ	irement of Act 74, Mich. P	.A. 1970, 94 JAN 21	PM 3 25
Newaygo (County)	Located In:	Corner Code ##	Marlen	a Tougood

Newaygo (County)	Located In:	Corner Code ##	m. In Toward
Public Land Survey	T 13N R 13W T R T R	A-3	Warlens Pougood.
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S T R S T R		Register of Deeds Stamp & File Number
	Recorded Plat		A B C D E F G H I J K L I

Norman L. Ochs I, Norman L. Cons , in a field survey on _______, 19 _____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

SW. Corner, Section 6, Sherman Twp., Newaygo Co., Mich.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1837 John Mullett 28" Beech S85°E 21 1ks. #1 6" Beech N36°E 331ks. #2

5-11-39 Lyle S.Shepherd#503 Witness Book #2 Pg. 19 2" Pipe

N.C.R.C. Sheet 2" Pipe

Corner Fence Post N45°E 42.7'#3 Corner Fence Post N45°W 43.1'#4

6-17-69 Newaygo Eng. & Survey Co. Set 1/2" Rod P. Pole S45 E 141.45' #7 6" Pine S20 E 116.60' #8 Tele. Pole S45 W 49.85' #5 Fence Corner Post N45 W 43.40' #4

Witness Book #2 Pg. 19

March 1968 Salisbury & Sanders

Set 1/2" Rod from wit. for CP. C3-26-84 Newaygo Fng. & Survey Co.

Tele. Pole \$45.0 \ 49.90" #5

Corner Fence Post N450 \ 43.1"#4

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Pence Corner Post N450 \ 43.40" #4

Fence Corner Post N450 \ 70.20" \ 70.2 NE. Cor. Tel. Riser S45°W 51.99' #10

12-03-93 found 1/2" pipe over 1/2" rod, rasised with S45°W 51. 1/2" Rod. replaced with 4" Harrison Cast Iron Monument. In 1968 Salis bury and Sanders did a section break of Sec. 7, Sherman Twp. for Consumers Power Co.. They set 1/2" rod from 1939 witnesses.

Condition of recorded witnesses is: #1 thru #6 Gone #7 Good Condition #8 Gone #9 and #10 Good Condition

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted 4" Harrison Monument as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

P. Pole S38°E 141.48' spike in NE. side of pole #7 NE. Corner Tel Riser S50°W 51.92' NE. Cor. Conc. B P. Pole N65°E 100.25' spike in SE side of pole #9 centerline of stop sign post S78°W 52.05' Base for riser #10

Signed by //Ohma

December 27, 1993 Date _

Surveyor's Michigan License No. 18. L.S. #22439

Approved by Peer Review Group December 27, 1993 Norman L. Ochs, County Representative

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED DAN., 1983

OF MICH

NORMAN L. OCHS

22439 ED LAND

SURVEY & REMONUMENTATION

JEC V 7 2000

RECTION