

MAR 02 1999

1998 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

'99 FEB 17 PM 3 38

| SECTION For corners in | | | 33 LED 1 | 1 PH 3 3 |
|--|--|---|--|--|
| Newaygo (County) | Located in: | Corner Code # | Linds | M. Brown |
| Public Land Survey Property Controlling in Section | T <u>13N</u> R <u>14W</u> T R T R T R S T R | F-7 | vol. $oldsymbol{2}$ | 213 |
| Miscellaneous Property in Sec. | STR STR | | Register of Deeds Stamp & File | Number |
| I. Norman L. Ochs do hereby certify that under repoints mentioned in lines 1 and therefore as required in the cu Department of the Interior, Bu Law and/or that the corner is conformance with the rules Decree of a Court of Law; est recovered, found as expressed | , in a field survey on <u>Decemb</u> quirements of P. A. 74, Michigan P. i 2 above were in conformance with arrent manual of survey instructions reau of Land Management or by a points mentioned in lines 3, 4 and of the Michigan Board of Land ablished, re-established, monument below: L corners, all in the same to | ner 16 , 19 98 , A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a ted, re-monumented, | A B C D E F G H I 2 - 6 - 5 - 4 - 3 - 3 4 - 7 - 8 - 9 - 10 - 5 6 - 18 - 17 - 16 - 15 - 7 8 - 19 - 20 - 21 - 22 - 9 10 - 30 - 29 - 28 - 27 - 11 12 - 31 - 32 - 33 - 34 - 34 | - 2 - 1 - - 11 - 12 - - 14 - 13 - - 23 - 24 - - 26 - 25 - - 14 - 25 - |
| North One Qurater Corner | , Section 21, Dayton Township, | Newaygo County, Michigan. | | |

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Mullett 1838 24" Beech N17°W 44 Links (29.04')#1. 12" Beech S70°W 18 Links (11.88')#2

Lyle S. Shepherd R.L.S. #503 Book 47, Page 80 April 11, 1916 Found Stone. No witnesses given. Norman L. Ochs R.L.S. #22439

LCRC #625 September 21, 1984 Found large rock with pointed end up, on centerline of road and on line with a fence running North and South. Removed stone and set 1/2" Rod and cap #22439 in monument box.

Guy Pole S02°W 30.70' #3 Power Pole North 31.27' #4 Power Pole N17°W 231.09' #5

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1/2" X 18" Rerod with cap #22439 in monument box on line ± with the North and South tree and brush row and field divisions. The centerline of the East and West bituminous road is 1.5 feet ± South. The condition of the recorded witnesses are: #1 and #2 gone, #3 thru #5 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rerod with cap and set a 23/2" diameter Harrison cast iron monument 20" long marked "County Survey" in a new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

| Guy Pole S02°W 30.75' Found spike in East side of pole. #3 Power Pole N02°E 31.05' Set spike with tag #22439 in East si Power Pole N77°W 230.86' Set spike with tag #22439 in Sout ½" X 18" Rerod with cap #22439 in ditch (6" ± below grad) S7 | th side of pole. #5 |
|--|---|
| Signed by Norman L. Ochs | Date December 18, 1998 |
| Surveyor's Michigan License No. 22439 | Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971 Revised May 14, 1975 |
| Approved by Peer Review Group on <u>December 22, 1998</u> Norman I., Ochs, County Representative. | Revised Jan., 1983 |

M.80.

