SURVEY & REMONUMENTATION

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

MAR 02 1999

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PM 3 38

1

T R T R T R T R T R R T T R R T R R T R	For corners in Carlon Newaygo (County)	Located in:	Corner Code #	Linda M.	Drown
in Section S_T_R Property in Sec. S_T_R Register of Deeds Stamp & File Number 4. Lot No, Recorded Plat	1. Public Land Survey	TR	F-13	YOL. $oldsymbol{2}$	213
4. Lot No, Recorded Plat	in Section 3. Miscellaneous	STR STR		Register of Deeds Stamp & Fil	e Number
South One Quarter Corner Section 33 Poston Tournehin November County November 12 $\frac{12}{31} + \frac{32}{32} + \frac{33}{33} + \frac{34}{35} + \frac{3}{3}$	I, Norman L. Ochs do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curred Department of the Interior, Burea Law and/or that the corner point conformance with the rules of Decree of a Court of Law; estably recovered, found as expressed by Note: Not more than 4 c	_, in a field survey on	. of 1970, the corner egulations and rules fithe United States decree of a Court of 5 above were in Surveyors or by a ed, re-monumented,	1	- 2 - 1 - - 11 - 12 - - 14 - 13 - - 23 - 24 -
13	recorded on this co	ertificate.	- ' •	12 - 31 + 32 + 33 + 34 + 34	35 - 36 -

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Mullett and Brookfield 1837 6" Beech N48°W 22 Links (14.52')#1 6" Sugar N47°E 11 Links (7.26')#2

William Fries, Jr. R.L.S. #30389 LCRC #1028 August 6, 1990 Found empty Monument Box Iron and Cap #30389 North 50.00' #7 Power Pole \$72°E 142.93' #7 Power Pole S12°E 44.46' #8 3" Pipe S01°W 52.71' #9

James E. Evans R.L.S. #22431 November 11, 1981 Drawing Number 81117B Found 3/2" Pipe in Monument Box 8" Locust N40°W 43.60' #3 30" Elm South 27.60' #4 North One Quarter Corner, Section 4, T12N R14W. East 16.57' #5

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 11/2" X 16" Iron Pipe in monument box and the centerline of the East and West bituminous road is 2 feet North and the chain-link fence going North is 3 feet East. The condition of the recorded witnesses are: #1 thru #4 gone, #5 thru #9 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Iron Pipe and monument box and set a 2¾" X 20" Harrison cast iron monument marked "County Survey" in a new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

North One Quarter Corner,	Section 4, T12N R14W (23/2	" X 20" Harrison cast iron monu	ment in monument box)
East 16.65' #5	(2)4	A 20 Hambor Cast I of Holla	

1/2" Rerod with cap #30389 North 50,05' #6

Power Pole S70°E 142.90' Found spike in Northeasterly side of pole. #7

Power Pole S05°E 44.50' Found P.K. nail with tag "Advanced Survey & Map" in West side of pole. #8

3" diameter Pipe (8 feet tall) S05°E 52.50' #9

Power Pole N35°W 53.80' Found P.K. nail with tag #22439 in Easterly side of pole.

14" Elm N45°W 91.28' Found spike in Easterly side of tree.

16" Locust North 103.60' Found spike in West side of tree.

Signed by // Mman 0	(Ochs)	Date	October 15, 1998
Norman L. Ochs			
Surveyor's Michigan License No	22439	Form approv	ed by Michigan State Board

Approved by Peer Review Group on October 22, 1998 Norman L. Ochs, County Representative.

