

MAR 1 3 2000

1999 Newaygo County Remonumentation Project REGISTER OF DEEDS

NEWAYGO COUNTY LIMBA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE

	FILING REQUIR	EMENT of Act 74, Mich	. P.A. 1970 UU FEB 28	Pri I II.
For corners in Newaygo (County)	Located in:	Corner Code #	Linea 7.	n. Brown
1. Public Land Survey	T <u>14N</u> R <u>13W</u> T <u>14N</u> R <u>14W</u> T <u>15N</u> R <u>14W</u> T <u>15N</u> R <u>13W</u>	A-1 / M-1 M-13 A-13	' VOL. $oldsymbol{2}$	354
 Property Controlling In Section Miscellaneous Property in Sec. 	STR STR STR		Register of Deeds_Stamp 8	. File Number
4. Lot No, Record 5. Private Claims	ded Plat	BCDEFG	HIJKL	
I. Norman L. Ochs do hereby certify that under requipoints mentioned in lines 1 and 2 therefore as required in the curre Department of the Interior, Burea Law and/or that the corner poinconformance with the rules of	, in a field survey on October Sirements of P. A. 74, Michigan P.A above were in conformance with rint manual of survey instructions of u of Land Management or by a sints mentioned in lines 3, 4 and the Michigan Board of Land shed, re-established, monument	a. of 1970, the corner egulations and rules of the United States decree of a Court of 5 above were in Surveyors or by a	2 - 6 - 5 - 4 - 3 4 - 7 - 8 - 9 - 1 5 - 18 - 17 - 16 - 1 7 - 8 - 19 - 20 - 21 - 2	1 1 1
Note: Not more than 4 c recorded on this ce	orners, all in the same to ertificate.	wn and range, may be	9 10 - 30 - 29 - 28 - 2	7 - 26 - 25 -
Northeast Corner, Section 1, Southeast Corner, Section 36	Lincoln Township, Newaygo (Denver Township, Newaygo (5, Beaver Township, Newaygo 1, Merrill Township, Newaygo	County, Michigan. County, Michigan.	11 12 31 - 32 - 33 - 3	4 - 35 - 36 -
A. DESCRIPTION OF OR	RIGINAL MONUMENT ANI	O ACCESSORIES AND/	OR SUBSEQUENT REST	ORATION:
G.L.O. Mullett and Brookfield 1838 9" Cedar (no bearing given) 16 Links (10.56')#1 16" Hemlock N40°E 35 Links (23.1')#2 William M. Jacques (County Surveyor) Book 44 Page 17 November 3, 1913 Found old stake.		Norman C. Caldwell R.L.S. #12018 LCRC #1124 July 1991 Placed 36" x 30" with brass cap aluminum monument. Centerline of old two track road 3 feet below surface. 8" Maple S48°W 47.45' #3 6" Maple N56°E 39.30' #4 6" Maple S87°E 9.80' #5 Carsonite Witness Post West 7.7' #6		
B. DESCRIPTION OF CORRESTABLISHING CORP	PRNER EVIDENCE FOUNI NER:	D AND/OR METHOD AI	PPLIED IN RESTORING C	PR
Found brass cap on top of feet North. The condition of	rod in the centerline of the	North and South trail ro are: #1 and #2 gone, #3	ead. Woven fence on grou	nd going West is 33
C. DESCRIPTION OF MC	NUMENT FOR CORNER CORNER:	AND ACCESSORIES E	STABLISHED TO PERPE	ETUATE LOCATING
Accepted brass cap on top reestablishment of the pos	o of rod as a substantial ma ition of the original corner.	arker for the section corr	ner and is accepted as a ca	reful and faithful
10" Maple N60°E 39.37' Fo 8" Maple S86°E 9.86' Four Carsonite Witness Post N8 6" diameter by 41's Steel P	ost N30°W 40.55'	le of tree. #4 e of tree. #5	ber 22, 1999	
Norman L. Ochs Surveyor's Michigan License No. 22439 Form approved			by Michigan State Board of Land Surveyors, Jan 28, 1971	
Approved by Peer Review Group on Norman L. Ochs, County Represe		_ 	OF MICH	evised May 14, 1975 Revised Jan., 1983

NORMAN L. OCHS