SUTIVEY & REMONUNCENTATION

MAR 0 2 1999

SECTION

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PM 3 39

Property and an arrangement of the second se				_ •
For corners in Newaygo	Located in:	Comer Order	1	
(County)	Located III.	Corner Code #	Linda M	. Dioue
1. Public Land Survey	T <u>14N</u> R <u>13W</u> T <u>14N</u> R <u>14W</u> T R T R	A-7 / M-7	vol. 2	24
2. Property Controlling in Section	STR STR			
Miscellaneous Property in Sec.	STR STR		Register of Deeds Stamp & File	Number
points mentioned in lines 1 and therefore as required in the cur Department of the Interior, Bur Law and/or that the corner p conformance with the rules of	, in a field survey on <u>December 1</u> quirements of P. A. 74, Michigan P.A. of 2 above were in conformance with regularent manual of survey instructions of the eau of Land Management or by a decreoints mentioned in lines 3, 4 and 5 at 6 the Michigan Board of Land Survey blished, re-established, monumented of	1970, the corner ations and rules United States ee of a Court of above were in	A B C D E F G H I 2 - 6 - 5 - 4 - 3 - 3 4 - 7 - 8 - 9 - 10 - 5 6 - 18 - 17 - 16 - 15 - 15 8 - 19 - 20 - 21 - 22 - 9	14 - 13 -
Note: Not more than 4 recorded on this	corners, all in the same town certificate.	and range, may be	10 30 + 29 + 28 + 27 +	26 + 25 -
Southeast Corner.	18, Lincoln Township, Newaygo Co Section 13, Denver Town RIGINAL MONUMENT AND AC	Shin Morney	12 31 + 32 + 33 + 34 + 13 County, Michigan. /OR SUBSEQUENT RESTORA	لسلت

G.L.O. Mullett and Brookfield 1838 Resurvey 10" Hemlock S55°W 35 Links (23.1')#1 12" Hemlock N65°W 44 Links (29.04')#2

Newaygo County Road Commission Sheet 1/2" Iron 24" Elm N17°E 78.45' #3
Power Pole S88°E 94.75' #4

Delos G. Anderson (County Surveyor)
June 17, 1897 Book A, Page 205
March 26, 27, 28, 1902 Book A, Pages 341 and 342
Stone Corner.

OVER &

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ½" Rerod (driven thru cap) presumed used to raise 6" diameter Concrete Monument with brass plate. The centerline of the North and South bituminous road is 5 feet ± West and there is no apparent East and West occupation. The condition of the recorded witnesses are: #1 thru #3 gone, #4 and #5 good condition, #6 gone, #7 thru #9 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted ½" Rerod over the 6" diameter Concrete Monument with brass plate as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Power Pole S85°E 95.04' Found spike in North side of pole. #4

36" White Oak S80°E 153.60' Found nail with tag (Advanced Survey & Map) in South side of base of tree. #7 14" Cherry (blazed) S16°E 53.43' Found spike in Westerly side of tree. #7

½" Rerod with cap #30389 West 33.04' #8

30" White Oak (blazed) N15°E 133.90' Found spike with tag (Advance Survey & Map) in West side of tree. #9 Cut "X" in Large Stope (36" diameter, 18" aboye grade) S85°W 30.68'

Signed by Norman L. Ochs

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyor to 20 4074

 Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Revised May 14, 1975 Revised Jan., 1983

Norman L. Ochs, County Representative.



A. Description (cont.)

George Blass R.L.S. #5489 June 23, 1961 LCRC #277

Located corner site from aerial photograph and government notes. Found ½" X 15" reinforcing Rod in gravel road North and South, Power line West, corner was 4 feet East of the centerline of the North and South road. From the witnesses of the Newaygo County Road Commission I placed a 6" diameter by 5 feet long reinforced Concrete Monument 1 foot below the surface of the road, at the recovered corner point. The monument is capped by a 3½" diameter brass tablet. 30" Elm (scribed B.T. 18) N15°E 78.55'#3

16" White Oak (scribed B.T. 19) S83°E 153.10' #5

14" Twin Elm (scribed B.T. 19) S16°E 80.43' #6

Norman L. Ochs R.L.S. #22439 January 8, 1975 Found Concrete Monument Power Pole S88°E 95.11' #4 10" Cherry S20°E 53.48' #7 24" Elm Stump N17°E 78.45' #3

William Fries, Jr. R.L.S. #30389 September 1995 ½" Iron and cap 24" White Oak N09°E 133.90' #9 Power Pole East 94.98' 34 29" White Oak S85°E 153.26' #5 ½" Iron and cap #30389 N89°W 33.00' #8

Norman L. Ochs R.L.S. #22439
August 8, 1996 Drawing Number 96210B
Found ½" Rod and cap #30389
Power Pole S88°E 95.11' #4
10" Twin Cherry S20°E 53.48' #7
½" Rod and cap #30389 West 33.00' #8
28" White Oak N20°E 134.00' #10

SURVEY & REMOTURE EVITION

MAR 0 2 1999

SECTION