MAR 02 1999

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PN 3 39

For corners in Newaygo (County)	Located in:	Corner Code#	Linds M. L	Jeour
Public Land Survey	T <u>14N</u> R <u>13W</u> T <u>14N</u> R <u>14W</u> TR	A-8 /	VOL. 2	24
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp & File N	umber
do hereby certify that under re- points mentioned in lines 1 and therefore as required in the cu Department of the Interior, Bur Law and/or that the corner p conformance with the rules o	in a field survey on <u>Februs</u> quirements of P. A. 74, Michigan P. I 2 above were in conformance with rrent manual of survey instructions reau of Land Management or by a points mentioned in lines 3, 4 an of the Michigan Board of Land ablished, re-established, monumen	A. of 1970, the corner regulations and rules of the United States decree of a Court of d 5 above were in Surveyors or by a	A B C D E F G H I J 2 - 6 - 5 - 4 - 3 - 2 3	- 13 -
Note: Not more than 4 recorded on this	corners, all in the same to certificate.	own and range, may be	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	
East One Quarter (Section 19, Lincoln Township, Corner, Section 24, I DRIGINAL MONUMENT AN	Denver Township, No	** ' ' ' ' ' ' '	

G.L.O. Mullett and Brookfield 1838 7" Beech S48°W 23 Links (15.18')#1 8" Beech N33°W 40 Links (26.4')#2

Newaygo County Road Commission Sheet 1/2" Iron Power Pole N22°E 117.2' #3 Fence Post S86°E 24.7' #4

Norman L. Ochs R.L.S. #22439 **Drawing Number 92415B** Power Pole N22°E 117.65' #3 Fence Post S88°E 24.47' #4 Fence Post S88°W 33,82' #8 14" - 14" Twin Cherry S20°E 112.34' #7 George Blass R.L.S. #5489 LCRC #278 June 23, 1961

Found 5/8" Iron reinforcing Rod in gravel road North and South in line with very old fences East and West 3 feet East of centerline of road North and South from witnesses of Newaygo County Road Commission.

Set 6" diameter by 5 foot long reinforced Concrete Monument 16" White Oak N05°E 186.00' #5 22" Twin Red Oak N88°E 236.15' #6

8" Triple White Cherry S10°E 110.86' #7

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1" diameter X 8" Rod over 3" diameter brass cap in 6" concrete cylinder and the centerline of the North and South road is 3.5 feet West. The fence line going East is 3 feet South and on field line going West. The condition of the recorded witnesses are: #1 and #2 gone, #3 and #4 good condition, #5 stump, #6 thru #8 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Date

Removed Rod and set a 23/2" X 20" Harrison cast iron monument marked "County Survey" over concrete cylinder as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

Power Pole N26°E 117.55' Found spike in West side of pole. #3
Fence Post S82°E 24.54' Found spike in South side of post, #4
16" Stump N11°E 186.3' to center. #5
22" - 38" Twin Red Oak S88°E 237.68' Set spike with tag #22439 in South side of tree. #6
16" - 21" White Cherry S05°E 112.28' Middle of both trees found spike in West side of tree. #7
Fence Post S88°W 33.92' Found spike in south side of post. #8

November 10, 1998

Norman L. Ochs

November 5, 1998

Form approved by Michigan State Board of Land Surveyor Ave

Revised May 14, 1975 Revised Jan., 1983

NORMAN L: OCHS LAND SURVEYOR

22439

Norman L. Ochs, County Representative.

Surveyor's Michigan License No.

Approved by Peer Review Group on